Access Compliance Report
Public Rights-of-Way
(Curb Ramps)

cole®   **CHARLOTTE**

Intersection ID: 46179	**Main Street:** SEVEN_OAKS_DR	**Cross Street:** ROCKY_RIVER_RD	**Location:** SW
ADA ID: FF65A77572B0	**Ramp Type:** Directional1	**Initial Pass/Fail:** Pass **Overall Compliance:** No	**Severity Score:** 17.5

Codes/Mitigation Info/Possible Solution   Field Measurements/Component Compliance

Possible Solutions:

Remove & Replace Entire Ramp.
Remove & Replace Gutter.

Surveyor Notes:

DWS NAILS EXPOSED, CURB LIP
1.0

PROW/ADA:

Not Found, R304.5.3, R305, R302.7.2

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	142.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	57.0	No	Grade Break Slope (%)	5.5
Yes	Ramp Slope (%)	6.3	No	Grade Break XSlope (%)	7.1
Yes	Ramp XSlope (%)	1.2			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	9.3	N/A	Flare Slope RT (%)	11.4
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	72.5	No	DWS Provided?	No
Yes	Landing Width (in)	59.5	N/A	DWS Contrast?	No
Yes	Landing Slope (%)	1.8	N/A	DWS Length (in)	N/A
Yes	Landing X Slope (%)	0.9	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
N/A	Shared Landing?	No	N/A	DWS Offset RT (in)	N/A
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.6
No	Gutter Lip Ht (in)	0.3	No	Gutter X Slope (%)	6.1
N/A	Painted X Walk1?	No		Road Slope (%)	1.2
	X Walk 1 Direction	To NE		Road X Slope (%)	3.9
	X Walk 1 Width (in)	N/A		Clear Space?	Yes
	X Walk 1 Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	3.9	Yes	Storm Grate/Utility Hazard?	No
N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A No	Curb Slope (%)	22.9

Street 1 Name	**SEVEN OAKS DR**
Stop Condition-Street 1	**StopSign**
Street 2 Name	**N/A**
Stop Condition-Street 2	**N/A**

Total Cost: **$ 2350.00**