Access Compliance Report
Public Rights-of-Way
(Island Curb Cuts)

Intersection ID: 8113	**Main Street: ORR_RD**	**Cross Street: GRIER_RD**	**Location: NW**
ADA ID: 99375F699CDC	**Curb Cut Type: IslandRefuge3**	**Initial Pass/Fail: Fail**	**Overall Compliance: No** / **Severity Score: 36.25**

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Entire Refuge.

Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost: **$ 3000.00**

Field Measurements/Component Compliance

Compliance	Description	Data	Compliance	Description	Data
Yes	Refuge 1 Length (In)	49.0	N/A	Gutter 1 Ponding?	N/A
Yes	Refuge 1 Width (In)	61.0	N/A	Gutter 1 Lip Ht (In)	N/A
Yes	Refuge 1 Slope (%)	0.5	N/A	Gutter 1 Slope (%)	N/A
Yes	Refuge 1 X Slope (%)	0.0	N/A	Gutter 1 X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	DWS 1 Provided?	N/A
N/A	X Walk 1 Direction	To NE	N/A	DWS 1 Contrast?	N/A
N/A	X Walk 1 Width (In)	N/A	N/A	DWS 1 Length (In)	N/A
N/A	Road 1 Slope (%)	0.5	N/A	DWS 1 Full Width?	N/A
N/A	Road 1 X Slope (%)	1.5	N/A	DWS 1 Offset (In)	N/A
Yes	Refuge 2 Length (In)	54.0	N/A	Gutter 2 Ponding?	N/A
Yes	Refuge 2 Width (In)	62.0	N/A	Gutter 2 Lip Ht (In)	N/A
Yes	Refuge 2 Slope (%)	1.3	N/A	Gutter 2 Slope (%)	N/A
Yes	Refuge 2 X Slope (%)	1.1	N/A	Gutter 2 X Slope (%)	N/A
N/A	Painted X Walk2?	Yes	N/A	DWS 2 Provided?	N/A
N/A	X Walk 2 Direction	To SE	N/A	DWS 2 Contrast?	N/A
N/A	X Walk 2 Width (In)	113.0	N/A	DWS 2 Length (In)	N/A
N/A	Road 2 Slope (%)	0.5	N/A	DWS 2 Full Width?	N/A
N/A	Road 2 X Slope (%)	2.7	N/A	DWS 2 Offset (In)	N/A
Yes	Refuge 3 Length (in)	53.0	N/A	Gutter 3 Ponding?	N/A
Yes	Refuge 3 Width (in)	60.0	N/A	Gutter 3 Lip Ht (in)	N/A
Yes	Refuge 3 Slope (%)	2.1	N/A	Gutter 3 Slope (%)	N/A
Yes	Refuge 3 XSlope (%)	2.7	N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	Yes	N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	To W	N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	105.0	N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	0.3	N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	2.7	N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type	N/A	N/A	Storm Grate/Utility Type	N/A
N/A	Surface Condition	Good			