



ADA Compliance Cost Estimate *

Intersection Inventory & Compliance Cost Estimate

\$ 21472.00

- | | |
|--|---|
|  Curb Ramps - Compliant |  Curb Ramps - Adjacent |
|  Curb Ramps - Non Compliant | |
|  Island Curb Cuts - Compliant |  Island Curb Cuts - Adjacent |
|  Island Curb Cuts - Non Compliant | |
|  Signals - Compliant |  Signals - Adjacent |
|  Signals - Non Compliant | |
|  Transit Stops - Compliant |  Transit Stops - Adjacent |
|  Transit Stops - Non Compliant | |
|  Railroad Crossings - Compliant |  Railroad Crossings - Adjacent |
|  Railroad Crossings - Non Compliant | |
|  Accessible Parking - Compliant |  Accessible Parking - Adjacent |
|  Accessible Parking - Non Compliant | |

- | | |
|-------------------------------------|---|
| ● Heavings < 1" (Excluded)*** | ● Heavings < 1" |
| ● Heavings ≥ 1" (Excluded)*** | ● Heavings ≥ 1" |
| ● Uneven Heaving (Excluded)*** | ● Uneven Heaving |
| — Heaving Clusters (Excluded) | — Heaving Clusters |
| ▲ Sidewalk Joint Gap (Excluded)*** | ▲ Sidewalk Joint Gap |
| ■ Miscellaneous Obstruction | ◆ Commercial Entrance |
| ■ Missing Sidewalk Obstruction | ◆ Residential Entrance |
| ■ Other Obstruction | ✚ Commercial Entrance (within slope violation) |
| ■ Pole Post Hydrant Obstruction | ✚ Residential Entrance (within slope violation) |
| ■ Ponding Obstruction | |
| ■ Sidewalk Joint Obstruction | Cross Slope |
| ■ Sign Obstruction | 2 - 3% |
| ■ Storm Grate Obstruction | 3.01 - 4% |
| ■ Transit Obstruction | 4.01 - 5% |
| ■ Traffic Obstruction | 5.01% - 6% |
| ■ Tree Obstruction | 6.01 - 7% |
| ■ Utility Obstruction | 7.01 - 8% |
| ■ Vegetation Obstruction - Low | 8.01 - 9% |
| ■ Vegetation Obstruction - Overhead | 9.01 - 10% |
| — Sidewalk Collection Path | 10.01 - 12% |
| — Adjacent Sidewalk Collection Path | > 12% |
| — Buried Sidewalk | Running Slope |
| — Sidewalk Not Surveyed | 5 - 8.33% |
| — Missing Sidewalk Gap | 8.34% - 10% |
| — No Sidewalk on Block | 10.01 - 12.5% |
| | > 12.5% |

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.