

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

62.0

58.0

10.3

1.5

10.1

4.2

N/A

No

To E

N/A

0.6

3.5

N/A

N/A

Intersection ID: N/A Main Street: CRAIGHEAD RD Cross Street: N/A Location: SW Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 0 ADA ID: 7978D9E564A2 Ramp Type: Combination2Diag

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

Nο

No

N/A

1.3

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Data

N/A

N/A

N/A

N/A



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2 Two New Directional Ramps or Equivalent.

Remove & Replace Curb Ramp With

N/A

PROW/ADA

Not Found, R304.2.2, R304.5.3, R304.3.2

Total Cost:

None **ENTRANCE**

None

CRAIGHEAD RD

N/A N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction

Road Slope (%)

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp XSlope LT (%)

N/A

N/A

N/A

N/A

3200.00

N/A Ramp Length (in) 51.0 51.0 Yes Ramp Width (in) N/A Flare Type LT N/A N/A N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Landing Length (in) N/A N/A N/A Landing Width (in) N/A Landing Slope (%) N/A N/A Landing X Slope (%) N/A N/A Landing Curb? (Y/N) N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A No To SE X Walk 1 Width (in) N/A 2.6 X Walk 1 Slope (%) X Walk 1 X Slope (%) 0.3 N/A N/A Ramp inside XWalk1?



Road X Slope (%) 1.1 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 5.5



