


Intersection ID: 10035708	Main Street: REDDMAN_RD	Cross Street: N/A	Location:	NW
ADA ID: 8FFC9AAB0CE1	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 33.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			
	Surveyor Notes:		N/A			
	PROW/ADA:		Not Found, R304.5.1, R304.5.3			
	Street 1 Name		ENTRANCE			
	Stop Condition-Street 2		None			
	Street 2 Name		REDDMAN RD			
	Stop Condition-Street 1		None			
	Total Cost:		\$ 3200.00			

