

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3953Main Street: BENTHAVEN_LNCross Street: COLESHIRE_CTLocation:NWADA ID: AC39119964BBRamp Type: Directional1Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 33.75

ADA ID: AC39119964BB Ramp Type: Directional1			Initial I	Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33					33.75
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
		Possible Solutions:		Compliance Description		Data Compliance Description			Data
		Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	24.0	N/A	Grade Break?	N/A
i				No	Ramp Width (in)	46.0	N/A	Grade Break Slope (%)	0.0
8				Yes	Ramp Slope (%)	6.9	N/A	Grade Break XSlope (%)	0.0
NT NEWWEN IN				No	Ramp XSlope (%)	7.1			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
<u>E</u>		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
COLESHIRE_CT				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
L L				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
(C.)				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.1, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
		·		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	L			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	\			N/A	Painted X Walk1?	No		Road Slope (%)	7.5
Street 1 Name	COLESHIRE CT				X Walk 1 Direction	To S		Road X Slope (%)	6.5
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	7.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	6.5	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	9.6





