


To: BEARLING_WY



Intersection Inventory & Compliance Cost Estimate

Item Description	Total Count	Non Compliant Count	Cost
Curb Ramps	3	3	\$ 5550.00
Island Curb Cuts	0	0	\$ 0.00
Signal Push Buttons	0	0	\$ 0.00
Transit Stops	0	0	\$ 0.00
Railroad Crossings	0	0	\$ 0.00
Accessible Parking Spaces	0	0	\$ 0.00
Intersection SubTotal:			\$ 5550.00

Curb Ramps - Compliant	Curb Ramps - Adjacent
Curb Ramps - Non Compliant	
Island Curb Cuts - Compliant	Island Curb Cuts - Adjacent
Island Curb Cuts - Non Compliant	
Signals - Compliant	Signals - Adjacent
Signals - Non Compliant	
Transit Stops - Compliant	Transit Stops - Adjacent
Transit Stops - Non Compliant	
Railroad Crossings - Compliant	Railroad Crossings - Adjacent
Railroad Crossings - Non Compliant	
Accessible Parking - Compliant	Accessible Parking - Adjacent
Accessible Parking - Non Compliant	

- Cross Slope**
- | | |
|------------|-------------|
| 2 - 3% | 7.01 - 8% |
| 3.01 - 4% | 8.01 - 9% |
| 4.01 - 5% | 9.01 - 10% |
| 5.01% - 6% | 10.01 - 12% |
| 6.01 - 7% | > 12% |
- Running Slope**
- | |
|---------------|
| 5 - 8.33% |
| 8.34% - 10% |
| 10.01 - 12.5% |
| > 12.5% |

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.