


To: SAVANNAH_HILLS_DR



Intersection Inventory & Compliance Cost Estimate

Corridor Total: \$ 86054.00

 Curb Ramps - Compliant	 Curb Ramps - Adjacent
 Curb Ramps - Non Compliant	
 Island Curb Cuts - Compliant	 Island Curb Cuts - Adjacent
 Island Curb Cuts - Non Compliant	
 Signals - Compliant	 Signals - Adjacent
 Signals - Non Compliant	
 Transit Stops - Compliant	 Transit Stops - Adjacent
 Transit Stops - Non Compliant	
 Railroad Crossings - Compliant	 Railroad Crossings - Adjacent
 Railroad Crossings - Non Compliant	
 Accessible Parking - Compliant	 Accessible Parking - Adjacent
 Accessible Parking - Non Compliant	

- Legend**

Cross Slope

 - Heavings < 1" (Excluded)***
 - Heavings ≥ 1" (Excluded)***
 - Uneven Heaving (Excluded)***
 - Heaving Clusters (Excluded)
 - ▲ Sidewalk Joint Gap (Excluded)***
 - Miscellaneous Obstruction
 - Missing Sidewalk Obstruction
 - Other Obstruction
 - Pole Post Hydrant Obstruction
 - Ponding Obstruction
 - Sidewalk Joint Obstruction
 - Sign Obstruction
 - Storm Grate Obstruction
 - Transit Obstruction
 - Traffic Obstruction
 - Tree Obstruction
 - Utility Obstruction
 - Vegetation Obstruction - Low
 - Vegetation Obstruction - Overhead
 - Sidewalk Collection Path
 - Adjacent Sidewalk Collection Path
 - Buried Sidewalk
 - Sidewalk Not Surveyed
 - Missing Sidewalk Gap
 - No Sidewalk on Block

Running Slope

 - Heavings < 1"
 - Heavings ≥ 1"
 - Uneven Heaving
 - Heaving Clusters
 - ▲ Sidewalk Joint Gap
 - ◆ Commercial Entrance
 - ◆ Residential Entrance
 - ✚ Commercial Entrance (within slope violation)
 - ✚ Residential Entrance (within slope violation)

Cross Slope

Obstruction Type	Range
Heavings < 1" (Excluded)***	2 - 3%
Heavings ≥ 1" (Excluded)***	3.01 - 4%
Uneven Heaving (Excluded)***	4.01 - 5%
Heaving Clusters (Excluded)	5.01% - 6%
Sidewalk Joint Gap (Excluded)***	6.01 - 7%
Miscellaneous Obstruction	7.01 - 8%
Missing Sidewalk Obstruction	8.01 - 9%
Other Obstruction	9.01 - 10%
Pole Post Hydrant Obstruction	10.01 - 12%
Ponding Obstruction	> 12%
Sidewalk Joint Obstruction	
Sign Obstruction	
Storm Grate Obstruction	
Transit Obstruction	
Traffic Obstruction	
Tree Obstruction	
Utility Obstruction	
Vegetation Obstruction - Low	
Vegetation Obstruction - Overhead	
Sidewalk Collection Path	
Adjacent Sidewalk Collection Path	
Buried Sidewalk	
Sidewalk Not Surveyed	
Missing Sidewalk Gap	
No Sidewalk on Block	

Running Slope

Obstruction Type	Range
Heavings < 1"	5 - 8.33%
Heavings ≥ 1"	8.34% - 10%
Uneven Heaving	10.01 - 12.5%
Heaving Clusters	> 12.5%
Sidewalk Joint Gap	
Commercial Entrance	
Residential Entrance	
Commercial Entrance (within slope violation)	
Residential Entrance (within slope violation)	

*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.