




ADA Survey Summary				ADA Compliance Cost Estimate *				Intersection Inventory & Compliance Cost Estimate				Slope			
Item	Description	Quantity		Item	Description	Quantity	Unit Price	Item Cost	Item	Description	Total Count	Non Compliant Count	Cost		
1	Heavings less than 1"	0 EA		1	Heavings less than 1"	0 EA	\$ 100.00	\$ 0.00	Curb Ramps		1	1	\$ 1850.00	● Heavings < 1" (Excluded)***	● Heavings < 1"
2	Heavings 1" or greater	0 EA		2	Heavings 1" or greater	0 EA	\$ 400.00	\$ 0.00	Island Curb Cuts		0	0	\$ 0.00	● Heavings ≥ 1" (Excluded)***	● Heavings ≥ 1"
3	Uneven Heavings	0 EA		3	Uneven Heavings	0 EA	\$ 400.00	\$ 0.00	Signal Push Buttons		0	0	\$ 0.00	● Uneven Heaving (Excluded)***	● Uneven Heaving
4	Heaving Clusters	0 SY		4	Heaving Clusters	0 SY	\$ 75.00	\$ 0.00	Transit Stops		0	0	\$ 0.00	— Heaving Clusters (Excluded)	— Heaving Clusters
5	Sidewalk Joint Gaps	0 EA		5	Sidewalk Joint Gaps	0 EA	\$ 200.00	\$ 0.00	Railroad Crossings		0	0	\$ 0.00	▲ Sidewalk Joint Gap (Excluded)***	▲ Sidewalk Joint Gap
6	Miscellaneous Obstruction	0 EA		6	Miscellaneous Obstruction	0 EA	\$ 1500.00	\$ 0.00	Accessible Parking Spaces		0	0	\$ 0.00	■ Miscellaneous Obstruction	◆ Commercial Entrance
7	Missing Sidewalk Obstruction	0 EA		7	Missing Sidewalk Obstruction	0 EA	\$ 200.00	\$ 0.00	Intersection SubTotal:				\$ 1850.00	■ Missing Sidewalk Obstruction	◆ Residential Entrance
8	Other Obstruction	0 EA		8	Other Obstruction	0 EA	\$ 500.00	\$ 0.00	Corridor Total:				\$ 26270.00	■ Other Obstruction	⊕ Commercial Entrance (within slope violation)
9	Pole Post Hydrant Obstruction	0 EA		9	Pole Post Hydrant Obstruction	0 EA	\$ 5000.00	\$ 0.00						■ Pole Post Hydrant Obstruction	⊕ Residential Entrance (within slope violation)
10	Ponding Obstruction	0 EA		10	Ponding Obstruction	0 EA	\$ 400.00	\$ 0.00	■ Curb Ramps - Compliant					■ Ponding Obstruction	
11	Sidewalk Joint Obstruction	0 EA		11	Sidewalk Joint Obstruction	0 EA	\$ 100.00	\$ 0.00	■ Curb Ramps - Non Compliant					■ Sidewalk Joint Obstruction	■ Cross Slope
12	Sign Obstruction	0 EA		12	Sign Obstruction	0 EA	\$ 150.00	\$ 0.00	■ Island Curb Cuts - Compliant					■ Sign Obstruction	■ 2 - 3%
13	Storm Grate Obstruction	0 EA		13	Storm Grate Obstruction	0 EA	\$700.00	\$ 0.00	■ Island Curb Cuts - Non Compliant					■ Storm Grate Obstruction	■ 3.01 - 4%
14	Transit Obstruction	0 EA		14	Transit Obstruction	0 EA	\$500.00	\$ 0.00	■ Signals - Compliant					■ Transit Obstruction	■ 4.01 - 5%
15	Traffic Obstruction	0 EA		15	Traffic Obstruction	0 EA	\$2000.00	\$ 0.00	■ Signals - Non Compliant					■ Traffic Obstruction	■ 5.01% - 6%
16	Tree Obstruction	0 EA		16	Tree Obstruction	0 EA	\$500.00	\$ 0.00	■ Transit Stops - Compliant					■ Tree Obstruction	■ 6.01 - 7%
17	Utility Obstruction	0 EA		17	Utility Obstruction	0 EA	\$1500.00	\$ 0.00	■ Transit Stops - Non Compliant					■ Utility Obstruction	■ > 12%
18	Vegetation Obstruction - Low	0 EA		18	Vegetation Obstruction - Low	0 EA	\$150.00	\$ 0.00	■ Railroad Crossings - Compliant					■ Vegetation Obstruction - Low	■ Running Slope
19	Vegetation Obstruction - Overhead	0 EA		19	Vegetation Obstruction - Overhead	0 EA	\$150.00	\$ 0.00	■ Railroad Crossings - Non Compliant					■ Vegetation Obstruction - Overhead	■ 5 - 8.33%
20	Commercial Entrance	0 EA		20	Commercial Entrance (within slope violation)	0 EA	\$ 5000.00	\$ 0.00	■ Accessible Parking - Compliant					■ Sidewalk Collection Path	■ 8.34% - 10%
21	Residential Entrance	0 EA		21	Residential Entrance (within slope violation)	0 EA	\$ 3000.00	\$ 0.00	■ Accessible Parking - Non Compliant					■ Adjacent Sidewalk Collection Path	■ 10.01 - 12.5%
22	Total Sidewalk Length Assessed	0 LF		22	Running Slope Violations**	0 SY	\$ 75.00	\$ 0.00						■ Buried Sidewalk	■ > 12.5%
23	Average Sidewalk Width	0 IN		23	Cross Slope Violations	0 SY	\$ 75.00	\$ 0.00						■ Sidewalk Not Surveyed	
24	No Sidewalk on Block (Approx.)	671.079 LF		24	Running and Cross Slope Violations	0 SY	\$ 75.00	\$ 0.00						■ Missing Sidewalk Gap	
25	Missing Sidewalk Gaps (Approx.)	583.448 LF		25	Missing Sidewalk Gaps (Approx.)	583.448 LF	\$ 41.67	\$ 24420.00						■ No Sidewalk on Block	
26	Poor Surface Condition (Approx.)	0 LF		26	Poor Surface Condition (Approx.)	0 LF	\$ 41.67	\$ 0.00							
27	Buried Sidewalk (Approx.)	140.3 LF		27	Buried Sidewalk (Approx.)	140.3 LF	\$ 41.67	\$ 5940.00							
					Sidewalk SubTotal:			\$ 0.00							