

To:



Intersection Inventory & Compliance Cost Estimate				
Item Description	Total Count	Non Compliant Count	Cost	
Curb Ramps	1	1	\$	1850.00
Island Curb Cuts	0	0	\$	0.00
Signal Push Buttons	0	0	\$	0.00
Transit Stops	0	0	\$	0.00
Railroad Crossings	0	0	\$	0.00
Accessible Parking Spaces	0	0	\$	0.00
Intersection SubTotal:			\$	1850.00
Corridor Total:			\$	1850.00

 Curb Ramps - Compliant	 Curb Ramps - Adjacent
 Curb Ramps - Non Compliant	
 Island Curb Cuts - Compliant	 Island Curb Cuts - Adjacent
 Island Curb Cuts - Non Compliant	
 Signals - Compliant	 Signals - Adjacent
 Signals - Non Compliant	
 Transit Stops - Compliant	 Transit Stops - Adjacent
 Transit Stops - Non Compliant	
 Railroad Crossings - Compliant	 Railroad Crossings - Adjacent
 Railroad Crossings - Non Compliant	
 Accessible Parking - Compliant	 Accessible Parking - Adjacent
 Accessible Parking - Non Compliant	

*Note: ADA pedestrian issues corrective measure. The ADA

**Note: Additional investigation

The legend is organized into two main columns. The left column lists various obstruction types, each preceded by a colored dot or line segment. The right column lists slope categories, each preceded by a colored line segment. The obstruction types include: Heavings < 1" (Excluded)***, Heavings ≥ 1" (Excluded)***, Uneven Heaving (Excluded)***, Heaving Clusters (Excluded), Sidewalk Joint Gap (Excluded)***, Miscellaneous Obstruction, Missing Sidewalk Obstruction, Other Obstruction, Pole Post Hydrant Obstruction, Ponding Obstruction, Sidewalk Joint Obstruction, Sign Obstruction, Storm Grate Obstruction, Transit Obstruction, Traffic Obstruction, Tree Obstruction, Utility Obstruction, Vegetation Obstruction - Low, Vegetation Obstruction - Overhead, Sidewalk Collection Path, Adjacent Sidewalk Collection Path, Buried Sidewalk, Sidewalk Not Surveyed, Missing Sidewalk Gap, and No Sidewalk on Block. The slope categories are divided into Cross Slope and Running Slope, with specific percentage ranges for each.

Obstruction Type	Slope Category	Slope Range
Heavings < 1" (Excluded)***	Cross Slope	2 - 3%
Heavings ≥ 1" (Excluded)***		7.01 - 8%
Uneven Heaving (Excluded)***	Cross Slope	3.01 - 4%
Heaving Clusters (Excluded)		8.01 - 9%
Sidewalk Joint Gap (Excluded)***	Cross Slope	4.01 - 5%
Miscellaneous Obstruction		9.01 - 10%
Missing Sidewalk Obstruction	Cross Slope	5.01% - 6%
Other Obstruction		10.01 - 12%
Pole Post Hydrant Obstruction	Cross Slope	6.01 - 7%
Ponding Obstruction		> 12%
Sidewalk Joint Obstruction	Running Slope	5 - 8.33%
Sign Obstruction		8.34% - 10%
Storm Grate Obstruction	Running Slope	10.01 - 12.5%
Transit Obstruction		> 12.5%
Traffic Obstruction	Running Slope	
Tree Obstruction		
Utility Obstruction	Running Slope	
Vegetation Obstruction - Low		
Vegetation Obstruction - Overhead	Running Slope	
Sidewalk Collection Path		
Adjacent Sidewalk Collection Path	Running Slope	
Buried Sidewalk		
Sidewalk Not Surveyed	Running Slope	
Missing Sidewalk Gap		
No Sidewalk on Block	Running Slope	

*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.