
Corridor ID: CLEMSON-AV-020





ADA Survey Summary						
Item Description Quantity						
1	Heavings less than 1"	11 EA				
2	Heavings 1" or greater	7 EA				
3	Uneven Heavings	0 EA				
4	Heaving Clusters	7.973 SY				
5	Sidewalk Joint Gaps	0 EA				
6	Miscellaneous Obstruction	0 EA				
7	Missing Sidewalk Obstruction	0 EA				
8	Other Obstruction	1 EA				
9	Pole Post Hydrant Obstruction	0 EA				
10	Ponding Obstruction	0 EA				
<u>11</u>	Sidewalk Joint Obstruction	0 EA				
12	Sign Obstruction	0 EA				
13	Storm Grate Obstruction	0 EA				
14	Transit Obstruction	0 EA				
15	Traffic Obstruction	0 EA				
<u>16</u>	Tree Obstruction	0 EA				
17	Utility Obstruction	0 EA				
18	Vegetation Obstruction - Low	1 EA				
19	Vegetation Obstruction - Overhead	0 EA				
20	Commercial Entrance	0 EA				
21	Residential Entrance	10 EA				
22	Total Sidewalk Length Assessed 8	376.752 LF				
23	Average Sidewalk Width	38 IN				
24	No Sidewalk on Block (Approx.) 11	189.008 LF				
25	Missing Sidewalk Gaps (Approx.)	76.483 LF				
26	Poor Surface Condition (Approx.)	0 LF				
<u>27</u>	Buried Sidewalk (Approx.)	0 LF				

3 Uneven Heavings 0 EA \$ 400.00 \$ 4 Heaving Clusters 0 SY \$ 75.00 \$	
4 Heaving Clusters 0 SY \$ 75.00 \$	0.00 0.00 0.00
5 Sidewalk Joint Gaps 0 EA \$ 200.00 \$	0.00
6 Miscellaneous Obstruction 0 EA \$1500.00 \$	
7 Missing Sidewalk Obstruction 0 EA \$200.00 \$	0.00
8 Other Obstruction 1 EA \$ 500.00 \$	500.00
9 Pole Post Hydrant Obstruction 0 EA \$5000.00 \$	0.00
10 Ponding Obstruction 0 EA \$400.00 \$	0.00
11 Sidewalk Joint Obstruction 0 EA \$100.00 \$	0.00
12 Sign Obstruction 0 EA \$ 150.00 \$	0.00
13 Storm Grate Obstruction 0 EA \$700.00 \$	0.00
14 Transit Obstruction 0 EA \$500.00 \$	0.00
15 Traffic Obstruction 0 EA \$2000.00 \$	0.00
16 Tree Obstruction 0 EA \$500.00 \$	0.00
17 Utility Obstruction 0 EA \$1500.00 \$	0.00
18 Vegetation Obstruction - Low 1 EA \$150.00 \$	150.00
19 Vegetation Obstruction - Overhead 0 EA \$150.00 \$	0.00
20 Commercial Entrance (within slope violation) 0 EA \$5000.00 \$	0.00
21 Residential Entrance (within slope violation) 10 EA \$3000.00 \$ 30	00.00
22 Running Slope Violations** 0 SY \$75.00 \$	0.00
23 Cross Slope Violations 219.403 SY \$75.00 \$ 16	455.00

12.443 SY

76.483 LF

0 LF

0 LF

Quantity

1EA

Unit Price

\$ 100.00

\$ 75.00

\$41.67

\$41.67

\$41.67

\$

\$

\$

933.00

3080.00

\$ 48538.00

0.00

0.00

Item Cost

100.00

Item Description

1 Heavings less than 1"

24 Running and Cross Slope Violations

25 Missing Sidewalk Gaps (Approx.)

26 Poor Surface Condition (Approx.)

27 Buried Sidewalk (Approx.)

Sidewalk SubTotal:

	•	•	
Item Description	Total Count	Non Compliant Count	Co
Curb Ramps	2	2	\$ 3700.0

Curb Ramps	:	2		2	\$ 3700.00
Island Curb Cuts	(0		0	\$ 0.00
Signal Push Buttons	(0		0	\$ 0.00
Transit Stops	(0		0	\$ 0.00
Railroad Crossings	(0		0	\$ 0.00
Accessible Parking Spaces	(0		0	\$ 0.00
Intersection SubTotal:				\$	3700.00

Corridor Total:

ક્ષ	Curb Ramps - Compliant	Ł	Curb Ramps - Adjacen
ક્ષ	Curb Ramps - Non Compliant		
•	Island Curb Cuts - Compliant	44	Island Curb Cuts - Adja
*	Island Curb Cuts - Non Compliant		
#	Signals - Compliant	#	Signals - Adjacent
#	Signals - Non Compliant		
	Transit Stops - Compliant		Transit Stops - Adjacer

- Railroad Crossings Compliant Railroad Crossings - Non Compliant Accessible Parking - Compliant Accessible Parking - Adjacent
- Accessible Parking Non Compliant

Transit Stops - Non Compliant

- Heavings ≥ 1" (Excluded)***
- Missing Sidewalk Obstruction

- Railroad Crossings Adjacent

Heavings < 1" (Excluded)***

Heavings < 1"

Heavings ≥ 1"

Uneven Heaving

Heaving Clusters

Sidewalk Joint Gap

Commercial Entrance

Residential Entrance

- Uneven Heaving (Excluded)***
- Heaving Clusters (Excluded)
- Sidewalk Joint Gap (Excluded)***
- Miscellaneous Obstruction
- Other Obstruction Commercial Entrance (within slope violation) Residential Entrance (within slope violation) Pole Post Hydrant Obstruction 55318.00 Ponding Obstruction **Cross Slope** Sidewalk Joint Obstruction 2 - 3% 7.01 - 8% 3.01 - 4% Sign Obstruction **8.01 - 9%** Storm Grate Obstruction 4.01 - 5% 9.01 - 10% jacent **Transit Obstruction** 5.01% - 6% 10.01 - 12% Traffic Obstruction 6.01 - 7% > 12% Tree Obstruction **Running Slope Utility Obstruction** 5 - 8.33% Vegetation Obstruction - Low 8.34% - 10% Vegetation Obstruction - Overhead **1**0.01 - 12.5% Sidewalk Collection Path > 12.5% Adjacent Sidewalk Collection Path **Buried Sidewalk** Sidewalk Not Surveyed Missing Sidewalk Gap No Sidewalk on Block

*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

^{**}Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.