


To: HERITAGE_WOODS_PL



Intersection Inventory & Compliance Cost Estimate

Corridor Total: \$ 4428.00

 Curb Ramps - Compliant	 Curb Ramps - Adjacent
 Curb Ramps - Non Compliant	
 Island Curb Cuts - Compliant	 Island Curb Cuts - Adjacent
 Island Curb Cuts - Non Compliant	
 Signals - Compliant	 Signals - Adjacent
 Signals - Non Compliant	
 Transit Stops - Compliant	 Transit Stops - Adjacent
 Transit Stops - Non Compliant	
 Railroad Crossings - Compliant	 Railroad Crossings - Adjacent
 Railroad Crossings - Non Compliant	
 Accessible Parking - Compliant	 Accessible Parking - Adjacent
 Accessible Parking - Non Compliant	

- | | |
|-------------------------------------|---|
| ● Heavings < 1" (Excluded)*** | ● Heavings < 1" |
| ● Heavings ≥ 1" (Excluded)*** | ● Heavings ≥ 1" |
| ● Uneven Heaving (Excluded)*** | ● Uneven Heaving |
| — Heaving Clusters (Excluded) | — Heaving Clusters |
| ▲ Sidewalk Joint Gap (Excluded)*** | ▲ Sidewalk Joint Gap |
| ■ Miscellaneous Obstruction | ◆ Commercial Entrance |
| ■ Missing Sidewalk Obstruction | ◆ Residential Entrance |
| ■ Other Obstruction | ⊕ Commercial Entrance (within slope violation) |
| ■ Pole Post Hydrant Obstruction | ⊕ Residential Entrance (within slope violation) |
| ■ Ponding Obstruction | |
| ■ Sidewalk Joint Obstruction | |
| ■ Sign Obstruction | |
| ■ Storm Grate Obstruction | |
| ■ Transit Obstruction | |
| ■ Traffic Obstruction | |
| ■ Tree Obstruction | |
| ■ Utility Obstruction | |
| ■ Vegetation Obstruction - Low | |
| ■ Vegetation Obstruction - Overhead | |
| — Sidewalk Collection Path | |
| — Adjacent Sidewalk Collection Path | |
| — Buried Sidewalk | |
| — Sidewalk Not Surveyed | |
| — Missing Sidewalk Gap | |
| — No Sidewalk on Block | |

Cross Slope	
2 - 3%	7.01 - 8%
3.01 - 4%	8.01 - 9%
4.01 - 5%	9.01 - 10%
5.01% - 6%	10.01 - 12%
6.01 - 7%	> 12%

Running Slope	
5 - 8.33%	
8.34% - 10%	
10.01 - 12.5%	
> 12.5%	

*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.