

An aerial photograph of a road intersection. A yellow label with the text 'CURRIER RD' is overlaid on the image, rotated 90 degrees counter-clockwise. A white pedestrian crossing icon is visible on the road surface.

DELUCA_DR



*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.