


E_7TH_ST

ARMORY_DR

An aerial photograph of a parking lot with several cars. A yellow text overlay 'LOUISE_AV' is positioned diagonally across the upper right. A wheelchair icon is located in the lower left corner of the image.



*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.