

To: BIRCHWOOD_DR



Intersection Inventory & Compliance Cost Estimate				
Item Description	Total Count	Non Compliant Count		Cost
Curb Ramps	0	0	\$	0.00
Island Curb Cuts	0	0	\$	0.00
Signal Push Buttons	0	0	\$	0.00
Transit Stops	0	0	\$	0.00
Railroad Crossings	0	0	\$	0.00
Accessible Parking Spaces	0	0	\$	0.00
Intersection SubTotal:			\$	0.00

Curb Ramps - Compliant	Curb Ramps - Adjacent
Curb Ramps - Non Compliant	
Island Curb Cuts - Compliant	Island Curb Cuts - Adjacent
Island Curb Cuts - Non Compliant	
Signals - Compliant	Signals - Adjacent
Signals - Non Compliant	
Transit Stops - Compliant	Transit Stops - Adjacent
Transit Stops - Non Compliant	
Railroad Crossings - Compliant	Railroad Crossings - Adjacent
Railroad Crossings - Non Compliant	
Accessible Parking - Compliant	Accessible Parking - Adjacent
Accessible Parking - Non Compliant	

Cross Slope

2 - 3%	7.01 - 8%
3.01 - 4%	8.01 - 9%
4.01 - 5%	9.01 - 10%
5.01% - 6%	10.01 - 12%
6.01 - 7%	> 12%

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.