Corridor ID: GLOXINIA-RD-001





ADA Survey Summary				
Ite	m Description	Quantity		
1	Heavings less than 1"	13 EA		
2	Heavings 1" or greater	0 EA		
3	Uneven Heavings	0 EA		
4	Heaving Clusters	0 SY		
5	Sidewalk Joint Gaps	0 EA		
6	Miscellaneous Obstruction	0 EA		
7	Missing Sidewalk Obstruction	0 EA		
8	Other Obstruction	0 EA		
9	Pole Post Hydrant Obstruction	0 EA		
10	Ponding Obstruction	0 EA		
11	Sidewalk Joint Obstruction	0 EA		
12	Sign Obstruction	0 EA		
13	Storm Grate Obstruction	0 EA		
14	Transit Obstruction	0 EA		
15	Traffic Obstruction	0 EA		
16	Tree Obstruction	0 EA		
17	Utility Obstruction	0 EA		
18	Vegetation Obstruction - Low	0 EA		
19	Vegetation Obstruction - Overhead	4 EA		
20	Commercial Entrance	0 EA		
21	Residential Entrance	12 EA		
22	Total Sidewalk Length Assessed	935.008 LF		
23	Average Sidewalk Width	48 IN		
24	No Sidewalk on Block (Approx.)	0 LF		
25	Missing Sidewalk Gaps (Approx.)	0 LF		
26	Poor Surface Condition (Approx.)	0 LF		
<u>27</u>	Buried Sidewalk (Approx.)	0 LF		

Item Description Qu		Quantity	Unit Price	Item Cost	
1_	Heavings less than 1"	5 EA	\$ 100.00	\$	500.00
2	Heavings 1" or greater	0 EA	\$ 400.00	\$	0.00
3	Uneven Heavings	0 EA	\$ 400.00	\$	0.00
4	Heaving Clusters	0 SY	\$ 75.00	\$	0.00
5	Sidewalk Joint Gaps	0 EA	\$ 200.00	\$	0.00
6	Miscellaneous Obstruction	0 EA	\$ 1500.00	\$	0.00
7	Missing Sidewalk Obstruction	0 EA	\$ 200.00	\$	0.00
8	Other Obstruction	0 EA	\$ 500.00	\$	0.00
9	Pole Post Hydrant Obstruction	0 EA	\$ 5000.00	\$	0.00
10	Ponding Obstruction	0 EA	\$ 400.00	\$	0.00
11	Sidewalk Joint Obstruction	0 EA	\$ 100.00	\$	0.00
12	Sign Obstruction	0 EA	\$ 150.00	\$	0.00
13	Storm Grate Obstruction	0 EA	\$700.00	\$	0.00
14	Transit Obstruction	0 EA	\$500.00	\$	0.00
15	Traffic Obstruction	0 EA	\$2000.00	\$	0.00
16	Tree Obstruction	0 EA	\$500.00	\$	0.00
17	Utility Obstruction	0 EA	\$1500.00	\$	0.00
18	Vegetation Obstruction - Low	0 EA	\$150.00	\$	0.00
19	Vegetation Obstruction - Overhead	4 EA	\$150.00	\$	600.00
20	Commercial Entrance (within slope violation	on) 0 EA	\$ 5000.00	\$	0.00
21	Residential Entrance (within slope violatio	n) 12 EA	\$ 3000.00	\$	36000.00
22	Running Slope Violations**	0 SY	\$ 75.00	\$	0.00
23	3 Cross Slope Violations 235.		\$ 75.00	\$	17686.00
24	Running and Cross Slope Violations	0 SY	\$ 75.00	\$	0.00
25	Missing Sidewalk Gaps (Approx.)	0 LF	\$ 41.67	\$	0.00
26	Poor Surface Condition (Approx.)	0 LF	\$ 41.67	\$	0.00
27	Buried Sidewalk (Approx.)	0 LF	\$ 41.67	\$	0.00
	Sidewalk SubTotal:			\$	54786.00

Intersection Inventory & Compliance Cost Estimate

Item Description	Total Count	Non Compliant Count	Cost
Curb Ramps	3	3	\$ 9000.00
Island Curb Cuts	0	0	\$ 0.00
Signal Push Buttons	0	0	\$ 0.00
Transit Stops	0	0	\$ 0.00
Railroad Crossings	0	0	\$ 0.00
Accessible Parking Spa	ces 0	0	\$ 0.00
Intersection SubTotal:	·	\$	9000.00

Corridor Total:

<u>Ł</u>	Curb Ramps - Compliant		
હે.	Curb Ramps - Non Compliant		
•	Island Curb Cuts - Compliant		
•	Island Curb Cuts - Non Compliant		
#	Signals - Compliant		
49:	Signals - Non Compliant		

- Transit Stops Non Compliant Railroad Crossings - Compliant
- Railroad Crossings Non Compliant Accessible Parking - Compliant
- Accessible Parking Non Compliant

tem Description	Total Count	Non Compliant Count		Cost	
Curb Ramps	3	3	\$	9000.00	
sland Curb Cuts	0	0	\$	0.00	
Signal Push Buttons	0	0	\$	0.00	_
Transit Stops	0	0	\$	0.00	
Railroad Crossings	0	0	\$	0.00	
Accessible Parking Spa	ces 0	0	\$	0.00	
Intersection SubTotal:		\$		9000.00	

Curb Ramps - Compliant	Curb Ramps - Adjacent
Curb Ramps - Non Compliant	
Island Curb Cuts - Compliant	Island Curb Cuts - Adjacent
Island Curb Cuts - Non Compliant	
Signals - Compliant	Signals - Adjacent
Signals - Non Compliant	
Transit Stops - Compliant	☐ Transit Stops - Adjacent

- Railroad Crossings Adjacent
- Accessible Parking Adjacent

Heavings < 1" Heavings < 1" (Excluded)***

Heavings ≥ 1"

Uneven Heaving

Heaving Clusters

Commercial Entrance

Residential Entrance

Sidewalk Joint Gap

- Heavings ≥ 1" (Excluded)*** Uneven Heaving (Excluded)***
- Heaving Clusters (Excluded)
- Sidewalk Joint Gap (Excluded)*** Miscellaneous Obstruction
- Missing Sidewalk Obstruction
- Other Obstruction

Commercial Entrance (within slope violation) Residential Entrance (within slope violation) Pole Post Hydrant Obstruction 63786.00 Ponding Obstruction **Cross Slope** Sidewalk Joint Obstruction 2 - 3% 7.01 - 8% 3.01 - 4% Sign Obstruction 8.01 - 9% Storm Grate Obstruction 4.01 - 5% 9.01 - 10% Transit Obstruction 5.01% - 6% 10.01 - 12% Traffic Obstruction 6.01 - 7% > 12% Tree Obstruction **Running Slope Utility Obstruction** 5 - 8.33% Vegetation Obstruction - Low 8.34% - 10% Vegetation Obstruction - Overhead 10.01 - 12.5% Sidewalk Collection Path > 12.5% Adjacent Sidewalk Collection Path **Buried Sidewalk** Sidewalk Not Surveyed Missing Sidewalk Gap No Sidewalk on Block

*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

^{**}Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.