




### Intersection Inventory & Compliance Cost Estimate

| Item               | Description                       | Quantity   |
|--------------------|-----------------------------------|------------|
| 1                  | Heavings less than 1"             | 13 EA      |
| 2                  | Heavings 1" or greater            | 0 EA       |
| 3                  | Uneven Heavings                   | 0 EA       |
| 4                  | Heaving Clusters                  | 1.776 SY   |
| 5                  | Sidewalk Joint Gaps               | 0 EA       |
| 6                  | Miscellaneous Obstruction         | 0 EA       |
| 7                  | Missing Sidewalk Obstruction      | 0 EA       |
| 8                  | Other Obstruction                 | 0 EA       |
| 9                  | Pole Post Hydrant Obstruction     | 0 EA       |
| 10                 | Ponding Obstruction               | 0 EA       |
| 11                 | Sidewalk Joint Obstruction        | 0 EA       |
| 12                 | Sign Obstruction                  | 0 EA       |
| 13                 | Storm Grate Obstruction           | 0 EA       |
| 14                 | Transit Obstruction               | 0 EA       |
| 15                 | Traffic Obstruction               | 0 EA       |
| 16                 | Tree Obstruction                  | 0 EA       |
| 17                 | Utility Obstruction               | 0 EA       |
| 18                 | Vegetation Obstruction - Low      | 0 EA       |
| 19                 | Vegetation Obstruction - Overhead | 0 EA       |
| 20                 | Commercial Entrance               | 0 EA       |
| 21                 | Residential Entrance              | 7 EA       |
| 22                 | Total Sidewalk Length Assessed    | 447.776 LF |
| 23                 | Average Sidewalk Width            | 48 IN      |
| 24                 | No Sidewalk on Block (Approx.)    | 410.506 LF |
| 25                 | Missing Sidewalk Gaps (Approx.)   | 0 LF       |
| 26                 | Poor Surface Condition (Approx.)  | 0 LF       |
| 27                 | Buried Sidewalk (Approx.)         | 0 LF       |
| Sidewalk SubTotal: |                                   |            |

| Item Description                                 | Quantity  | Unit Price | Item Cost   |
|--------------------------------------------------|-----------|------------|-------------|
| 1 Heavings less than 1"                          | 6 EA      | \$ 100.00  | \$ 600.00   |
| 2 Heavings 1" or greater                         | 0 EA      | \$ 400.00  | \$ 0.00     |
| 3 Uneven Heavings                                | 0 EA      | \$ 400.00  | \$ 0.00     |
| 4 Heaving Clusters                               | 0 SY      | \$ 75.00   | \$ 0.00     |
| 5 Sidewalk Joint Gaps                            | 0 EA      | \$ 200.00  | \$ 0.00     |
| 6 Miscellaneous Obstruction                      | 0 EA      | \$ 1500.00 | \$ 0.00     |
| 7 Missing Sidewalk Obstruction                   | 0 EA      | \$ 200.00  | \$ 0.00     |
| 8 Other Obstruction                              | 0 EA      | \$ 500.00  | \$ 0.00     |
| 9 Pole Post Hydrant Obstruction                  | 0 EA      | \$ 5000.00 | \$ 0.00     |
| 10 Ponding Obstruction                           | 0 EA      | \$ 400.00  | \$ 0.00     |
| 11 Sidewalk Joint Obstruction                    | 0 EA      | \$ 100.00  | \$ 0.00     |
| 12 Sign Obstruction                              | 0 EA      | \$ 150.00  | \$ 0.00     |
| 13 Storm Grate Obstruction                       | 0 EA      | \$700.00   | \$ 0.00     |
| 14 Transit Obstruction                           | 0 EA      | \$500.00   | \$ 0.00     |
| 15 Traffic Obstruction                           | 0 EA      | \$2000.00  | \$ 0.00     |
| 16 Tree Obstruction                              | 0 EA      | \$500.00   | \$ 0.00     |
| 17 Utility Obstruction                           | 0 EA      | \$1500.00  | \$ 0.00     |
| 18 Vegetation Obstruction - Low                  | 0 EA      | \$150.00   | \$ 0.00     |
| 19 Vegetation Obstruction - Overhead             | 0 EA      | \$150.00   | \$ 0.00     |
| 20 Commercial Entrance (within slope violation)  | 0 EA      | \$ 5000.00 | \$ 0.00     |
| 21 Residential Entrance (within slope violation) | 4 EA      | \$ 3000.00 | \$ 12000.00 |
| 22 Running Slope Violations**                    | 0 SY      | \$ 75.00   | \$ 0.00     |
| 23 Cross Slope Violations                        | 54.321 SY | \$ 75.00   | \$ 4074.00  |
| 24 Running and Cross Slope Violations            | 30.239 SY | \$ 75.00   | \$ 2268.00  |
| 25 Missing Sidewalk Gaps (Approx.)               | 0 LF      | \$ 41.67   | \$ 0.00     |
| 26 Poor Surface Condition (Approx.)              | 0 LF      | \$ 41.67   | \$ 0.00     |
| 27 Buried Sidewalk (Approx.)                     | 0 LF      | \$ 41.67   | \$ 0.00     |
| Sidewalk SubTotal:                               |           |            | \$ 18942.00 |

| Item Description          | Total Count | Non Compliant Count | Cost       |
|---------------------------|-------------|---------------------|------------|
| Curb Ramps                | 2           | 2                   | \$ 3700.00 |
| Island Curb Cuts          | 0           | 0                   | \$ 0.00    |
| Signal Push Buttons       | 0           | 0                   | \$ 0.00    |
| Transit Stops             | 0           | 0                   | \$ 0.00    |
| Railroad Crossings        | 0           | 0                   | \$ 0.00    |
| Accessible Parking Spaces | 0           | 0                   | \$ 0.00    |
| Intersection SubTotal:    |             |                     | \$ 3700.00 |

Corridor Total:

\$ 22642.00

Curb Ramps - Compliant

Curb Ramps - Non Compliant

Island Curb Cuts - Compliant

Island Curb Cuts - Non Compliant

Signals - Compliant

Signals - Non Compliant

Transit Stops - Compliant

Transit Stops - Non Compliant

Railroad Crossings - Compliant

Railroad Crossings - Non Compliant

Accessible Parking - Compliant

Accessible Parking - Non Compliant

Curb Ramps - Adjacent

Island Curb Cuts - Adjacent

Signals - Adjacent

Transit Stops - Adjacent

Railroad Crossings - Adjacent

Accessible Parking - Adjacent

Heavings < 1" (Excluded)\*\*\*

Heavings ≥ 1" (Excluded)\*\*\*

Uneven Heaving (Excluded)\*\*\*

Heaving Clusters (Excluded)

Sidewalk Joint Gap (Excluded)\*\*\*

Miscellaneous Obstruction

Missing Sidewalk Obstruction

Other Obstruction

Pole Post Hydrant Obstruction

Ponding Obstruction

Sidewalk Joint Obstruction

Sign Obstruction

Storm Grate Obstruction

Transit Obstruction

Traffic Obstruction

Tree Obstruction

Utility Obstruction

Vegetation Obstruction - Low

Vegetation Obstruction - Overhead

Sidewalk Collection Path

Adjacent Sidewalk Collection Path

Buried Sidewalk

Sidewalk Not Surveyed

Missing Sidewalk Gap

No Sidewalk on Block

Heavings < 1"

Heavings ≥ 1"

Uneven Heaving

Heaving Clusters

Sidewalk Joint Gap

Commercial Entrance

Residential Entrance

Commercial Entrance (within slope violation)

Residential Entrance (within slope violation)

Cross Slope

2 - 3%

7.01 - 8%

3.01 - 4%

8.01 - 9%

4.01 - 5%

9.01 - 10%

5.01% - 6%

10.01 - 12%

6.01 - 7%

> 12%

Running Slope

5 - 8.33%

8.34% - 10%

10.01 - 12.5%

> 12.5%

\*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

\*\*Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

\*\*\*Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.