
Access Compliance Report - Public Rights-of-Way (Corridor: Sidewalk & Intersection Items)

Corridor ID: MABLE-HUBBARD-DR-010





	ADA Survey Summary				
Ite	m Description	Quantity			
1_	Heavings less than 1"	0 EA			
2	Heavings 1" or greater	0 EA			
3	Uneven Heavings	0 EA			
4	Heaving Clusters	0 SY			
5	Sidewalk Joint Gaps	0 EA			
6	Miscellaneous Obstruction	0 EA			
7	Missing Sidewalk Obstruction	0 EA			
8	Other Obstruction	0 EA			
9	Pole Post Hydrant Obstruction	0 EA			
10	Ponding Obstruction	0 EA			
<u>11</u>	Sidewalk Joint Obstruction	0 EA			
12	Sign Obstruction	0 EA			
13	Storm Grate Obstruction	0 EA			
14	Transit Obstruction	0 EA			
<u>15</u>	Traffic Obstruction	0 EA			
16	Tree Obstruction	0 EA			
17	Utility Obstruction	0 EA			
18	Vegetation Obstruction - Low	0 EA			
19	Vegetation Obstruction - Overhead	0 EA			
20	Commercial Entrance	0 EA			
21	Residential Entrance	0 EA			
22	Total Sidewalk Length Assessed	0 LF			
23	Average Sidewalk Width	0 IN			
24	No Sidewalk on Block (Approx.) 86	64.742 LF			
25	Missing Sidewalk Gaps (Approx.)	0 LF			
26	Poor Surface Condition (Approx.)	0 LF			
27	Buried Sidewalk (Approx.)	0 LF			

ADA Compliance Cost Estimate *					
Item Description	Quantity	Unit Price	Iten	n Cost	
1 Heavings less than 1"	0 EA	\$ 100.00	\$	0.00	
2 Heavings 1" or greater	0 EA	\$ 400.00	\$	0.00	
3 Uneven Heavings	0 EA	\$ 400.00	\$	0.00	
4 Heaving Clusters	0 SY	\$ 75.00	\$	0.00	
5 Sidewalk Joint Gaps	0 EA	\$ 200.00	\$	0.00	
6 Miscellaneous Obstruction	0 EA	\$ 1500.00	\$	0.00	
7 Missing Sidewalk Obstruction	0 EA	\$ 200.00	\$	0.00	
8 Other Obstruction	0 EA	\$ 500.00	\$	0.00	
9 Pole Post Hydrant Obstruction	0 EA	\$ 5000.00	\$	0.00	
10 Ponding Obstruction	0 EA	\$ 400.00	\$	0.00	
11 Sidewalk Joint Obstruction	0 EA	\$ 100.00	\$	0.00	
12 Sign Obstruction	0 EA	\$ 150.00	\$	0.00	
13 Storm Grate Obstruction	0 EA	\$700.00	\$	0.00	
14 Transit Obstruction	0 EA	\$500.00	\$	0.00	
15 Traffic Obstruction	0 EA	\$2000.00	\$	0.00	
16 Tree Obstruction	0 EA	\$500.00	\$	0.00	
17 Utility Obstruction	0 EA	\$1500.00	\$	0.00	
18 Vegetation Obstruction - Low	0 EA	\$150.00	\$	0.00	
19 Vegetation Obstruction - Overhead	0 EA	\$150.00	\$	0.00	
20 Commercial Entrance (within slope violat	ion) 0 EA	\$ 5000.00	\$	0.00	
21 Residential Entrance (within slope violation	on) 0 EA	\$ 3000.00	\$	0.00	
22 Running Slope Violations**	0 SY	\$ 75.00	\$	0.00	
23 Cross Slope Violations	0 SY	\$ 75.00	\$	0.00	
24 Running and Cross Slope Violations	0 SY	\$ 75.00	\$	0.00	
25 Missing Sidewalk Gaps (Approx.)	0 LF	\$ 41.67	\$	0.00	
26 Poor Surface Condition (Approx.)	0 LF	\$ 41.67	\$	0.00	
27 Buried Sidewalk (Approx.)	0 LF	\$ 41.67	\$	0.00	
Sidewalk SubTotal:			\$	0.00	

em Cost	Item
0.00	Curb
0.00	Island
0.00	Signa
0.00	Trans
0.00	Railro
0.00	Acces
0.00	Inters
0.00	
0.00	Cor
0.00	
0.00	<u>k</u>
0.00	Ġ.
0.00	•
0.00	4
0.00	8
0.00	8
0.00	
0.00	
0.00	⊗
0.00	⊗
0.00	ક્ષ
0.00	ક્ષ
0.00	
0.00	
0.00	

Item Description	Total Count	Non	Compliant Count		Cost
Curb Ramps	0		0	\$	0.00
Island Curb Cuts	0		0	\$	0.00
Signal Push Buttons	0		0	\$	0.00
Transit Stops	0		0	\$	0.00
Railroad Crossings	0		0	\$	0.00
Accessible Parking Spa	ces 0		0	\$	0.00
				ተ	0.00
Intersection SubTotal:			;	\$	0.00
Corridor Total:			\$	Φ	0.00
	•	<u>E</u>		*	0.00
Corridor Total: Curb Ramps - C Curb Ramps - N Island Curb Cuts	on Compliant		\$	jace	0.00

rri	dor Total:		\$ 0.00	
Ł	Curb Ramps - Compliant	Ġ.	Curb Ramps - Adjacent	
ġ.	Curb Ramps - Non Compliant			
•	Island Curb Cuts - Compliant	۵	Island Curb Cuts - Adjacent	
ů.	Island Curb Cuts - Non Compliant			
#	Signals - Compliant	*	Signals - Adjacent	
#	Signals - Non Compliant			
	Transit Stops - Compliant		Transit Stops - Adjacent	
	Transit Stops - Non Compliant			
※	Railroad Crossings - Compliant	\otimes	Railroad Crossings - Adjacent	
※	Railroad Crossings - Non Compliant			
Ġ.	Accessible Parking - Compliant	Ġ.	Accessible Parking - Adjacent	
ક્ષ	Accessible Parking - Non Compliant			

•	Heavings < 1" (Excluded)***	0	Heavings < 1"
•	Heavings ≥ 1" (Excluded)***		Heavings ≥ 1"
•	Uneven Heaving (Excluded)***		Uneven Heaving
	Heaving Clusters (Excluded)		Heaving Clusters
A	Sidewalk Joint Gap (Excluded)***	_	Sidewalk Joint Gap
	Miscellaneous Obstruction	•	Commercial Entrance
	Missing Sidewalk Obstruction	♦	Residential Entrance
	Other Obstruction	+	Commercial Entrance (within slope violation)
	Pole Post Hydrant Obstruction	4	Residential Entrance (within slope violation)
	Ponding Obstruction	Cros	s Slope
	Sidewalk Joint Obstruction		2 - 3% 7.01 - 8%
	Sign Obstruction		3.01 - 4% 8.01 - 9%
	Storm Grate Obstruction		4.01 - 5% 9.01 - 10%
	Transit Obstruction		5.01% - 6% 10.01 - 12%
	Traffic Obstruction		6.01 - 7% > 12%
	Tree Obstruction	Runr	ning Slope
	Utility Obstruction		5 - 8.33%
	Vegetation Obstruction - Low		8.34% - 10%
	Vegetation Obstruction - Overhead		10.01 - 12.5%
_	Sidewalk Collection Path		> 12.5%
	Adjacent Sidewalk Collection Path		
	Buried Sidewalk		
	Sidewalk Not Surveyed		
	Missing Sidewalk Gap		

*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.

No Sidewalk on Block