Corridor ID: MILLENNIUM-AV-004





ADA Survey Summary				
Ite	Quantity			
1_	Heavings less than 1"	5 EA		
2	Heavings 1" or greater	0 EA		
3	Uneven Heavings	0 EA		
4	Heaving Clusters	2.664 SY		
5	Sidewalk Joint Gaps	0 EA		
6	Miscellaneous Obstruction	0 EA		
7	Missing Sidewalk Obstruction	0 EA		
8	Other Obstruction	0 EA		
9	Pole Post Hydrant Obstruction	0 EA		
10	Ponding Obstruction	0 EA		
11	Sidewalk Joint Obstruction	0 EA		
12	Sign Obstruction	0 EA		
13	Storm Grate Obstruction	0 EA		
14	Transit Obstruction	0 EA		
15	Traffic Obstruction	0 EA		
16	Tree Obstruction	0 EA		
<u>17</u>	Utility Obstruction	0 EA		
18	Vegetation Obstruction - Low	0 EA		
19	Vegetation Obstruction - Overhead	0 EA		
20	Commercial Entrance	3 EA		
21	Residential Entrance	0 EA		
22	Total Sidewalk Length Assessed	499.301 LF		
23	Average Sidewalk Width	72 IN		
24	No Sidewalk on Block (Approx.)	0 LF		
25	Missing Sidewalk Gaps (Approx.)	0 LF		
26	Poor Surface Condition (Approx.)	0 LF		
<u>27</u>	Buried Sidewalk (Approx.)	0 LF		

ADA Compliance Co	st Estimate *
0	Hait Daine

Item Description		Quantity	Unit Price	Item Cost	
1_	Heavings less than 1"	4 EA	\$ 100.00	\$	400.00
2	Heavings 1" or greater	0 EA	\$ 400.00	\$	0.00
3	Uneven Heavings	0 EA	\$ 400.00	\$	0.00
4	Heaving Clusters	0 SY	\$ 75.00	\$	0.00
5	Sidewalk Joint Gaps	0 EA	\$ 200.00	\$	0.00
6	Miscellaneous Obstruction	0 EA	\$ 1500.00	\$	0.00
7	Missing Sidewalk Obstruction	0 EA	\$ 200.00	\$	0.00
8	Other Obstruction	0 EA	\$ 500.00	\$	0.00
9	Pole Post Hydrant Obstruction	0 EA	\$ 5000.00	\$	0.00
10	Ponding Obstruction	0 EA	\$ 400.00	\$	0.00
11	Sidewalk Joint Obstruction	0 EA	\$ 100.00	\$	0.00
12	Sign Obstruction	0 EA	\$ 150.00	\$	0.00
13	Storm Grate Obstruction	0 EA	\$700.00	\$	0.00
14	Transit Obstruction	0 EA	\$500.00	\$	0.00
15	Traffic Obstruction	0 EA	\$2000.00	\$	0.00
16	Tree Obstruction	0 EA	\$500.00	\$	0.00
17	Utility Obstruction	0 EA	\$1500.00	\$	0.00
18	Vegetation Obstruction - Low	0 EA	\$150.00	\$	0.00
19	Vegetation Obstruction - Overhead	0 EA	\$150.00	\$	0.00
20	Commercial Entrance (within slope violation	on) 2 EA	\$ 5000.00	\$	10000.00
21	Residential Entrance (within slope violation	n) 0 EA	\$ 3000.00	\$	0.00
22	Running Slope Violations**	0 SY	\$ 75.00	\$	0.00
23	Cross Slope Violations	40.557 SY	\$ 75.00	\$	3042.00
24	Running and Cross Slope Violations	0 SY	\$ 75.00	\$	0.00
25	Missing Sidewalk Gaps (Approx.)	0 LF	\$ 41.67	\$	0.00
26	Poor Surface Condition (Approx.)	0 LF	\$ 41.67	\$	0.00
27	Buried Sidewalk (Approx.)	0 LF	\$ 41.67	\$	0.00
	Sidewalk SubTotal:			\$	13442.00

## **Intersection Inventory & Compliance Cost Estimate**

Item Description	<b>Total Count</b>	Non Compliant Count	Cost
Curb Ramps	7	7	\$ 13050.00
Island Curb Cuts	0	0	\$ 0.00
Signal Push Buttons	0	0	\$ 0.00
Transit Stops	0	0	\$ 0.00
Railroad Crossings	0	0	\$ 0.00
Accessible Parking Space	es 1	1	\$ 250.00
Intersection SubTotal:		\$	13300.00

## **Corridor Total:**

Curb Ramps - Compliant	
------------------------	--

- Curb Ramps Non Compliant Island Curb Cuts - Compliant
- Island Curb Cuts Non Compliant
- Signals Compliant
- Signals Non Compliant
- Transit Stops Compliant Transit Stops - Non Compliant
- Railroad Crossings Compliant
- Railroad Crossings Non Compliant
- Accessible Parking Compliant
- Accessible Parking Non Compliant

- Curb Ramps Adjacent
- Island Curb Cuts Adjacent
- - Signals Adjacent
  - □ Transit Stops Adjacent
  - Railroad Crossings Adjacent
  - Accessible Parking Adjacent

- Heavings < 1" (Excluded)\*\*\*
- Heavings ≥ 1" (Excluded)\*\*\*
- Uneven Heaving (Excluded)\*\*\*
- Heaving Clusters (Excluded)
- Sidewalk Joint Gap (Excluded)\*\*\* Sidewalk Joint Gap Miscellaneous Obstruction Commercial Entrance Missing Sidewalk Obstruction Residential Entrance Other Obstruction Commercial Entrance (within slope violation) Residential Entrance (within slope violation) Pole Post Hydrant Obstruction 26742.00 Ponding Obstruction **Cross Slope** Sidewalk Joint Obstruction 2 - 3% 7.01 - 8% 3.01 - 4% Sign Obstruction 8.01 - 9% Storm Grate Obstruction 4.01 - 5% 9.01 - 10% Transit Obstruction 5.01% - 6% 10.01 - 12% Traffic Obstruction 6.01 - 7% > 12% Tree Obstruction **Running Slope Utility Obstruction** 5 - 8.33% Vegetation Obstruction - Low 8.34% - 10% Vegetation Obstruction - Overhead 10.01 - 12.5% > 12.5% Sidewalk Collection Path Adjacent Sidewalk Collection Path **Buried Sidewalk** Sidewalk Not Surveyed Missing Sidewalk Gap No Sidewalk on Block

Heavings < 1"

Heavings ≥ 1"

Uneven Heaving

Heaving Clusters

\*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

<sup>\*\*</sup>Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

\*\*\*Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.