
**Access Compliance Report - Public Rights-of-Way** (Corridor: Sidewalk & Intersection Items)

**Corridor ID: MULBERRY-CHURCH-RD-020** 





| ADA Survey Summary |                                   |            |  |  |
|--------------------|-----------------------------------|------------|--|--|
| Ite                | m Description                     | Quantity   |  |  |
| 1                  | Heavings less than 1"             | 12 EA      |  |  |
| 2                  | Heavings 1" or greater            | 1 EA       |  |  |
| 3                  | Uneven Heavings                   | 0 EA       |  |  |
| 4                  | Heaving Clusters                  | 0 SY       |  |  |
| 5                  | Sidewalk Joint Gaps               | 0 EA       |  |  |
| 6                  | Miscellaneous Obstruction         | 0 EA       |  |  |
| 7                  | Missing Sidewalk Obstruction      | 0 EA       |  |  |
| 8                  | Other Obstruction                 | 0 EA       |  |  |
| 9                  | Pole Post Hydrant Obstruction     | 0 EA       |  |  |
| 10                 | Ponding Obstruction               | 0 EA       |  |  |
| 11                 | Sidewalk Joint Obstruction        | 0 EA       |  |  |
| 12                 | Sign Obstruction                  | 0 EA       |  |  |
| 13                 | Storm Grate Obstruction           | 0 EA       |  |  |
| 14                 | Transit Obstruction               | 0 EA       |  |  |
| 15                 | Traffic Obstruction               | 0 EA       |  |  |
| 16                 | Tree Obstruction                  | 0 EA       |  |  |
| 17                 | Utility Obstruction               | 0 EA       |  |  |
| 18                 | Vegetation Obstruction - Low      | 0 EA       |  |  |
| 19                 | Vegetation Obstruction - Overhead | 0 EA       |  |  |
| 20                 | Commercial Entrance               | 0 EA       |  |  |
| 21                 | Residential Entrance              | 1 EA       |  |  |
| 22                 | Total Sidewalk Length Assessed    | 818.953 LF |  |  |
| 23                 | Average Sidewalk Width            | 60 IN      |  |  |
| 24                 | No Sidewalk on Block (Approx.)    | 0 LF       |  |  |
| 25                 | Missing Sidewalk Gaps (Approx.)   | 0 LF       |  |  |
| 26                 | Poor Surface Condition (Approx.)  | 0 LF       |  |  |
| 27                 | Buried Sidewalk (Approx.)         | 145.878 LF |  |  |

| Item Description Qu |  | Quantity   | Unit Price | Ite | em Cost  |
|---------------------|--|------------|------------|-----|----------|
| 1_                  | Heavings less than 1"                        | 4 EA       | \$ 100.00  | \$  | 400.00   |
| 2                   | Heavings 1" or greater                       | 0 EA       | \$ 400.00  | \$  | 0.00     |
| 3                   | Uneven Heavings                              | 0 EA       | \$ 400.00  | \$  | 0.00     |
| 4                   | Heaving Clusters                             | 0 SY       | \$ 75.00   | \$  | 0.00     |
| 5                   | Sidewalk Joint Gaps                          | 0 EA       | \$ 200.00  | \$  | 0.00     |
| 6                   | Miscellaneous Obstruction                    | 0 EA       | \$ 1500.00 | \$  | 0.00     |
| 7                   | Missing Sidewalk Obstruction                 | 0 EA       | \$ 200.00  | \$  | 0.00     |
| 8                   | Other Obstruction                            | 0 EA       | \$ 500.00  | \$  | 0.00     |
| 9                   | Pole Post Hydrant Obstruction                | 0 EA       | \$ 5000.00 | \$  | 0.00     |
| 10                  | Ponding Obstruction                          | 0 EA       | \$ 400.00  | \$  | 0.00     |
| 11                  | Sidewalk Joint Obstruction                   | 0 EA       | \$ 100.00  | \$  | 0.00     |
| 12                  | Sign Obstruction                             | 0 EA       | \$ 150.00  | \$  | 0.00     |
| 13                  | Storm Grate Obstruction                      | 0 EA       | \$700.00   | \$  | 0.00     |
| 14                  | Transit Obstruction                          | 0 EA       | \$500.00   | \$  | 0.00     |
| 15                  | Traffic Obstruction                          | 0 EA       | \$2000.00  | \$  | 0.00     |
| 16                  | Tree Obstruction                             | 0 EA       | \$500.00   | \$  | 0.00     |
| 17                  | Utility Obstruction                          | 0 EA       | \$1500.00  | \$  | 0.00     |
| 18                  | Vegetation Obstruction - Low                 | 0 EA       | \$150.00   | \$  | 0.00     |
| 19                  | Vegetation Obstruction - Overhead            | 0 EA       | \$150.00   | \$  | 0.00     |
| 20                  | Commercial Entrance (within slope violation  | on) 0 EA   | \$ 5000.00 | \$  | 0.00     |
| 21                  | Residential Entrance (within slope violation | n) 1 EA    | \$ 3000.00 | \$  | 3000.00  |
| 22                  | Running Slope Violations**                   | 0 SY       | \$ 75.00   | \$  | 0.00     |
| 23                  | Cross Slope Violations                       | 195.014 SY | \$ 75.00   | \$  | 14626.00 |
| 24                  | Running and Cross Slope Violations           | 52.484 SY  | \$ 75.00   | \$  | 3936.00  |
| 25                  | Missing Sidewalk Gaps (Approx.)              | 0 LF       | \$ 41.67   | \$  | 0.00     |
| 26                  | Poor Surface Condition (Approx.)             | 0 LF       | \$ 41.67   | \$  | 0.00     |

145.878 LF

\$41.67 \$ 6160.00

\$ 21962.00

27 Buried Sidewalk (Approx.)

Sidewalk SubTotal:

| Intersection Inventory & Compliance Cost Esti | mate |
|---|------|
|---|------|

| Item Description       | <b>Total Count</b> | Non Compliant Count | Cost          |
|------------------------|--------------------|---------------------|---------------|
| Curb Ramps             | 0                  | 0                   | \$<br>0.00    |
| Island Curb Cuts       | 0                  | 0                   | \$<br>0.00    |
| Signal Push Buttons    | 0                  | 0                   | \$<br>0.00    |
| Transit Stops          | 1                  | 1                   | \$<br>4650.00 |
| Railroad Crossings     | 0                  | 0                   | \$<br>0.00    |
| Accessible Parking Spa | ices 0             | 0                   | \$<br>0.00    |
| Intersection SubTotal: |                    | \$                  | 4650.00       |

| Corridor Total: | \$ | 26612.00 |
|-----------------|----|----------|
|                 | •  |          |

Accessible Parking - Adjacent

| Curb Ramps - Compliant             | Ġ.  | Curb Ramps - Adjacent   |
|------------------------------------|---|---|
| Curb Ramps - Non Compliant         |   |   |
| Island Curb Cuts - Compliant       | 44  | Island Curb Cuts - Adjacent   |
| Island Curb Cuts - Non Compliant   |   |   |
| Signals - Compliant                | ⓐ   | Signals - Adjacent  |
| Signals - Non Compliant            |   |   |
| Transit Stops - Compliant          |   | Transit Stops - Adjacent  |
| Transit Stops - Non Compliant      |   |   |
| Railroad Crossings - Compliant     | $\otimes$   | Railroad Crossings - Adjacent   |
| Railroad Crossings - Non Compliant |   |   |
|                                    | Curb Ramps - Non Compliant Island Curb Cuts - Compliant Island Curb Cuts - Non Compliant Signals - Compliant Signals - Non Compliant Transit Stops - Compliant Transit Stops - Non Compliant Railroad Crossings - Compliant | Curb Ramps - Non Compliant Island Curb Cuts - Compliant Island Curb Cuts - Non Compliant Signals - Compliant Signals - Non Compliant Transit Stops - Compliant Transit Stops - Non Compliant Railroad Crossings - Compliant |

Accessible Parking - Compliant

Accessible Parking - Non Compliant

| Heavings < 1" (Excluded)***       | Heavings < 1"                                 |
|-----------------------------------|---|
| Heavings ≥ 1" (Excluded)***       | Heavings ≥ 1"                                 |
| Uneven Heaving (Excluded)***      | Uneven Heaving                                |
| Heaving Clusters (Excluded)       | Heaving Clusters                              |
| Sidewalk Joint Gap (Excluded)***  | Sidewalk Joint Gap                            |
| Miscellaneous Obstruction         | Commercial Entrance                           |
| Missing Sidewalk Obstruction      | Residential Entrance                          |
| Other Obstruction                 | Commercial Entrance (within slope violation)  |
| Pole Post Hydrant Obstruction     | Residential Entrance (within slope violation) |
| Ponding Obstruction               | Cross Slope                                   |
| Sidewalk Joint Obstruction        | 2 - 3% 7.01 - 8%                              |
| Sign Obstruction                  | 3.01 - 4% 8.01 - 9%                           |
| Storm Grate Obstruction           | 4.01 - 5% 9.01 - 10%                          |
| Transit Obstruction               | 5.01% - 6% 10.01 - 12%                        |
| Traffic Obstruction               | 6.01 - 7% > 12%                               |
| Tree Obstruction                  | Running Slope                                 |
| Utility Obstruction               | 5 - 8.33%                                     |
| Vegetation Obstruction - Low      | 8.34% - 10%                                   |
| Vegetation Obstruction - Overhead | 10.01 - 12.5%                                 |
| Sidewalk Collection Path          | > 12.5%                                       |
| Adjacent Sidewalk Collection Path |   |

\*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

\*\*Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

\*\*\*Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.

**Buried Sidewalk** 

Sidewalk Not Surveyed Missing Sidewalk Gap No Sidewalk on Block