Corridor ID: QUINCEY-ST-010





ADA Survey Summary				
Item Description Quantit				
1	Heavings less than 1"	9 EA		
2	Heavings 1" or greater	0 EA		
3	Uneven Heavings	0 EA		
4	Heaving Clusters	0 SY		
5	Sidewalk Joint Gaps	0 EA		
6	Miscellaneous Obstruction	0 EA		
7	Missing Sidewalk Obstruction	0 EA		
8	Other Obstruction	0 EA		
9	Pole Post Hydrant Obstruction	0 EA		
10	Ponding Obstruction	0 EA		
<u>11</u>	Sidewalk Joint Obstruction	0 EA		
12	Sign Obstruction	0 EA		
13	Storm Grate Obstruction	0 EA		
14	Transit Obstruction	0 EA		
15	Traffic Obstruction	0 EA		
16	Tree Obstruction	0 EA		
<u>17</u>	Utility Obstruction	0 EA		
18	Vegetation Obstruction - Low	0 EA		
19	Vegetation Obstruction - Overhead	0 EA		
20	Commercial Entrance	5 EA		
21	Residential Entrance	0 EA		
22	Total Sidewalk Length Assessed 8	21.461 LF		
23	Average Sidewalk Width	66 IN		
24	No Sidewalk on Block (Approx.)	0 LF		
25	Missing Sidewalk Gaps (Approx.)	0 LF		
<u>26</u>	Poor Surface Condition (Approx.)	0 LF		

27 Buried Sidewalk (Approx.)

40.247 LF

Sidewalk SubTotal:

## ADA Compliance Cost Estimate \*

Ite	m Description	Quantity	Unit Price	lt	em Cost
1	Heavings less than 1"	3 EA	\$ 100.00	\$	300.00
2	Heavings 1" or greater	0 EA	\$ 400.00	\$	0.00
3	Uneven Heavings	0 EA	\$ 400.00	\$	0.00
4	Heaving Clusters	0 SY	\$ 75.00	\$	0.00
5	Sidewalk Joint Gaps	0 EA	\$ 200.00	\$	0.00
6	Miscellaneous Obstruction	0 EA	\$ 1500.00	\$	0.00
7	Missing Sidewalk Obstruction	0 EA	\$ 200.00	\$	0.00
8	Other Obstruction	0 EA	\$ 500.00	\$	0.00
9	Pole Post Hydrant Obstruction	0 EA	\$ 5000.00	\$	0.00
10	Ponding Obstruction	0 EA	\$ 400.00	\$	0.00
11	Sidewalk Joint Obstruction	0 EA	\$ 100.00	\$	0.00
12	Sign Obstruction	0 EA	\$ 150.00	\$	0.00
13	Storm Grate Obstruction	0 EA	\$700.00	\$	0.00
14	Transit Obstruction	0 EA	\$500.00	\$	0.00
15	Traffic Obstruction	0 EA	\$2000.00	\$	0.00
16	Tree Obstruction	0 EA	\$500.00	\$	0.00
17	Utility Obstruction	0 EA	\$1500.00	\$	0.00
18	Vegetation Obstruction - Low	0 EA	\$150.00	\$	0.00
19	Vegetation Obstruction - Overhead	0 EA	\$150.00	\$	0.00
20	Commercial Entrance (within slope violati	on) 5 EA	\$ 5000.00	\$	25000.00
21	Residential Entrance (within slope violation	on) 0 EA	\$ 3000.00	\$	0.00
22	Running Slope Violations**	0 SY	\$ 75.00	\$	0.00
23	Cross Slope Violations	198.133 SY	\$ 75.00	\$	14860.00
24	Running and Cross Slope Violations	0 SY	\$ 75.00	\$	0.00
25	Missing Sidewalk Gaps (Approx.)	0 LF	\$ 41.67	\$	0.00
26	Poor Surface Condition (Approx.)	0 LF	\$ 41.67	\$	0.00
27	Buried Sidewalk (Approx.)	40.247 LF	\$ 41.67	\$	1760.00

## Intersection Inventory & Compliance Cost Estimate

Item Description	<b>Total Count</b>	Non Compliant Count	Cost
Curb Ramps	3	3	\$ 8250.00
Island Curb Cuts	0	0	\$ 0.00
Signal Push Buttons	0	0	\$ 0.00
Transit Stops	0	0	\$ 0.00
Railroad Crossings	0	0	\$ 0.00
Accessible Parking Spa	ces 0	0	\$ 0.00
Intersection SubTotal:		\$	8250.00

## Corridor Total: \$ 48410.00

Ł	Curb Ramps - Compliant	ŧ.	Curb Ramps - Adjacent
Ġ.	Curb Ramps - Non Compliant		
•	Island Curb Cuts - Compliant	Δ	Island Curb Cuts - Adja
•	Island Curb Cuts - Non Compliant		
#	Signals - Compliant	#	Signals - Adjacent
#	Signals - Non Compliant		
	Transit Stops - Compliant		Transit Stops - Adjacen
	Transit Stops - Non Compliant		
<b>⊗</b>	Railroad Crossings - Compliant	$\otimes$	Railroad Crossings - Ad
<b>⊗</b>	Railroad Crossings - Non Compliant		

Accessible Parking - Adjacent

Accessible Parking - Compliant

\$ 40160.00

Accessible Parking - Non Compliant

- Heavings < 1" (Excluded)\*\*\*

  Heavings < 1"
- Heavings ≥ 1" (Excluded)\*\*\*
- Uneven Heaving (Excluded)\*\*\*
- Heaving Clusters (Excluded)
- Sidewalk Joint Gap (Excluded)\*\*\*
- Miscellaneous Obstruction
- Missing Sidewalk Obstruction
- Other Obstruction
- Pole Post Hydrant Obstruction
- Ponding Obstruction
- Sidewalk Joint Obstruction
- Sign Obstruction
- Storm Grate Obstruction
- Transit Obstruction
- Traffic Obstruction
- Tree Obstruction
- Utility Obstruction
- Vegetation Obstruction Low
- Vegetation Obstruction Overhead
- Sidewalk Collection Path
- Adjacent Sidewalk Collection Path
- Buried Sidewalk
- Barioa Olaowan
- Sidewalk Not Surveyed
- Missing Sidewalk Gap
  - No Sidewalk on Block

	• (	Uneven Heaving
		Heaving Clusters
	<u> </u>	Sidewalk Joint Gap
	* (	Commercial Entrance
	<b>*</b> I	Residential Entrance
	+ (	Commercial Entrance (within slope violation)
	4	Residential Entrance (within slope violation)
	Cross	Slope
	2 -	7.01 - 8%
	3.0	01 - 4% 8.01 - 9%
	4.0	9.01 - 5%
	5.0	01% - 6% 10.01 - 12%
	6.0	01 - 7% > 12%
	Runnir	ng Slope
	5	- 8.33%
	8.	34% - 10%
ł	10	0.01 - 12.5%
	>	12.5%

Heavings ≥ 1"

\*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

\*\*Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

<sup>\*\*</sup>Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

\*\*\*Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.