


Access Compliance Report - Public Rights-of-Way (Corridor: Sidewalk & Intersection Items)

Corridor ID: S-I-77-HY-128





Corridor Total:

Item Desci	Quantity	
1 Heavin	gs less than 1"	0 EA
2 Heaving	gs 1" or greater	0 EA
	n Heavings	0 EA
4 Heavin	g Clusters	0 SY
5 Sidewa	ılk Joint Gaps	0 EA
6 Miscella	aneous Obstruction	0 EA
7 Missing	Sidewalk Obstruction	0 EA
8 Other C	Obstruction	0 EA
9 Pole Po	ost Hydrant Obstruction	0 EA
10 Pondin	g Obstruction	0 EA
11 Sidewa	lk Joint Obstruction	0 EA
12 Sign Ol	bstruction	0 EA
13 Storm (Grate Obstruction	0 EA
14 Transit	Obstruction	0 EA
15 Traffic	Obstruction	0 EA
16 Tree Ol	bstruction	0 EA
17 Utility C	Obstruction	0 EA
18 Vegeta	tion Obstruction - Low	0 EA
19 Vegeta	tion Obstruction - Overhead	0 EA
20 Comme	ercial Entrance	0 EA
21 Reside	ntial Entrance	0 EA
22 Total Si	idewalk Length Assessed	0 LF
23 Averag	e Sidewalk Width	0 IN
24 No Side	ewalk on Block (Approx.)	359.021 LF
25 Missing	Sidewalk Gaps (Approx.)	0 LF
26 Poor S	urface Condition (Approx.)	0 LF
27 Buried	Sidewalk (Approx.)	0 LF

ntity	Item Description	Quantity	Unit Price	Iten	n Cost
0 EA	1 Heavings less than 1"	0 EA	\$ 100.00	\$	0.00
0 EA	2 Heavings 1" or greater	0 EA	\$ 400.00	\$	0.00
0 EA	3 Uneven Heavings	0 EA	\$ 400.00	\$	0.00
0 SY	4 Heaving Clusters	0 SY	\$ 75.00	\$	0.00
0 EA	5 Sidewalk Joint Gaps	0 EA	\$ 200.00	\$	0.00
0 EA	6 Miscellaneous Obstruction	0 EA	\$ 1500.00	\$	0.00
0 EA	7 Missing Sidewalk Obstruction	0 EA	\$ 200.00	\$	0.00
0 EA	8 Other Obstruction	0 EA	\$ 500.00	\$	0.00
0 EA	9 Pole Post Hydrant Obstruction	0 EA	\$ 5000.00	\$	0.00
0 EA	10 Ponding Obstruction	0 EA	\$ 400.00	\$	0.00
0 EA	11 Sidewalk Joint Obstruction	0 EA	\$ 100.00	\$	0.00
0 EA	12 Sign Obstruction	0 EA	\$ 150.00	\$	0.00
0 EA	13 Storm Grate Obstruction	0 EA	\$700.00	\$	0.00
0 EA	14 Transit Obstruction	0 EA	\$500.00	\$	0.00
0 EA	15 Traffic Obstruction	0 EA	\$2000.00	\$	0.00
0 EA	16 Tree Obstruction	0 EA	\$500.00	\$	0.00
0 EA	17 Utility Obstruction	0 EA	\$1500.00	\$	0.00
0 EA	18 Vegetation Obstruction - Low	0 EA	\$150.00	\$	0.00
0 EA	19 Vegetation Obstruction - Overhead	0 EA	\$150.00	\$	0.00
0 EA	20 Commercial Entrance (within slope violat	ion) 0 EA	\$ 5000.00	\$	0.00
0 EA	21 Residential Entrance (within slope violation	on) 0 EA	\$ 3000.00	\$	0.00
0 LF	22 Running Slope Violations**	0 SY	\$ 75.00	\$	0.00
O IN	23 Cross Slope Violations	0 SY	\$ 75.00	\$	0.00
1 LF_	24 Running and Cross Slope Violations	0 SY	\$ 75.00	\$	0.00
0 LF	25 Missing Sidewalk Gaps (Approx.)	0 LF	\$ 41.67	\$	0.00
0 LF_	26 Poor Surface Condition (Approx.)	0 LF	\$ 41.67	\$	0.00
0 LF	27 Buried Sidewalk (Approx.)	0 LF	\$ 41.67	\$	0.00
	Sidewalk SubTotal:			\$	0.00

al Count	Non Compliant Count		Cost
0	0	_	
		\$	0.00
0	0	\$	0.00
0	0	\$	0.00
0	0	\$	0.00
0	0	\$	0.00
0	0	\$	0.00
	- :	\$	0.00
	0 0 0	0 0	0 0 \$

£	Curb Ramps - Compliant	Ġ	Curb Ramps - Adjacent
ę.	Curb Ramps - Non Compliant		
4	Island Curb Cuts - Compliant	44	Island Curb Cuts - Adjacent
4	Island Curb Cuts - Non Compliant		
#	Signals - Compliant	#	Signals - Adjacent
#	Signals - Non Compliant		

	·		-	
•	Island Curb Cuts - Non Compliant			
8	Signals - Compliant	*	Signals - Adjacent	
#	Signals - Non Compliant			
	Transit Stops - Compliant		Transit Stops - Adjacent	
	Transit Stops - Non Compliant			
※	Railroad Crossings - Compliant	\otimes	Railroad Crossings - Adjacent	-
※	Railroad Crossings - Non Compliant			-
ል	Accessible Parking - Compliant	Ġ.	Accessible Parking - Adjacent	-
Ł	Accessible Parking - Non Compliant			_

0.00

•	Heavings < 1" (Excluded)***	<u> </u>	Heavings < 1"
•	Heavings ≥ 1" (Excluded)***		Heavings ≥ 1"
•	Uneven Heaving (Excluded)***		Uneven Heaving
	Heaving Clusters (Excluded)		Heaving Clusters
A	Sidewalk Joint Gap (Excluded)***	A	Sidewalk Joint Gap
•	Miscellaneous Obstruction	•	Commercial Entrance
	Missing Sidewalk Obstruction	♦	Residential Entrance
	Other Obstruction	4	Commercial Entrance (within slope violation)
	Pole Post Hydrant Obstruction	4	Residential Entrance (within slope violation)
	Ponding Obstruction	Cross	s Slope
	Sidewalk Joint Obstruction	2	7.01 - 8%
	Sign Obstruction	3	8.01 - 4%
	Storm Grate Obstruction	4	.01 - 5% 9.01 - 10%
	Transit Obstruction	5	i.01% - 6% 10.01 - 12%
•	Traffic Obstruction	6	i.01 - 7% > 12%
	Tree Obstruction	Runn	ing Slope
	Utility Obstruction	;	5 - 8.33%
•	Vegetation Obstruction - Low		3.34% - 10%
	Vegetation Obstruction - Overhead		10.01 - 12.5%
	Sidewalk Collection Path	 ;	> 12.5%
	Adjacent Sidewalk Collection Path		
	Buried Sidewalk		

*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.

Sidewalk Not Surveyed Missing Sidewalk Gap No Sidewalk on Block