

To: DELSHIRE_LN



Intersection Inventory & Compliance Cost Estimate			
Item Description	Total Count	Non Compliant Count	Cost
Curb Ramps	0	0	\$ 0.00
Island Curb Cuts	0	0	\$ 0.00
Signal Push Buttons	0	0	\$ 0.00
Transit Stops	0	0	\$ 0.00
Railroad Crossings	0	0	\$ 0.00
Accessible Parking Spaces	0	0	\$ 0.00
Intersection SubTotal:			\$ 0.00
Corridor Total:		\$	13478.00

 Curb Ramps - Compliant	 Curb Ramps - Adjacent
 Curb Ramps - Non Compliant	
 Island Curb Cuts - Compliant	 Island Curb Cuts - Adjacent
 Island Curb Cuts - Non Compliant	
 Signals - Compliant	 Signals - Adjacent
 Signals - Non Compliant	
 Transit Stops - Compliant	 Transit Stops - Adjacent
 Transit Stops - Non Compliant	
 Railroad Crossings - Compliant	 Railroad Crossings - Adjacent
 Railroad Crossings - Non Compliant	
 Accessible Parking - Compliant	 Accessible Parking - Adjacent
 Accessible Parking - Non Compliant	

*Note: ADA pedestrian issues corrective measure. The ADA

**Note: Additional investigation

The legend is organized into two main columns. The left column lists various obstruction types, each preceded by a colored square or line segment. The right column lists slope categories, each preceded by a colored line segment. The legend is divided into two sections: 'Cross Slope' and 'Running Slope'.

Obstruction Type	Color	Slope Category	Color
Heavings < 1" (Excluded)***	Yellow circle	2 - 3%	Light red line
Heavings ≥ 1" (Excluded)***	Orange circle	3.01 - 4%	Light red line
Uneven Heaving (Excluded)***	Red circle	4.01 - 5%	Light red line
Heaving Clusters (Excluded)	Yellow line	5.01% - 6%	Light red line
Sidewalk Joint Gap (Excluded)***	Purple triangle	6.01 - 7%	Light red line
Miscellaneous Obstruction	Purple diamond	7.01 - 8%	Red line
Missing Sidewalk Obstruction	Pink square	8.01 - 9%	Red line
Other Obstruction	Blue square	9.01 - 10%	Red line
Pole Post Hydrant Obstruction	Orange square	10.01 - 12%	Red line
Ponding Obstruction	Light blue square	> 12%	Dark red line
Sidewalk Joint Obstruction	Yellow square		
Sign Obstruction	Gray square		
Storm Grate Obstruction	Blue square		
Transit Obstruction	Orange square		
Traffic Obstruction	Black square		
Tree Obstruction	Green square		
Utility Obstruction	Black square		
Vegetation Obstruction - Low	Green square		
Vegetation Obstruction - Overhead	Teal square		
Sidewalk Collection Path	Green line		
Adjacent Sidewalk Collection Path	Gray line		
Buried Sidewalk	Orange line		
Sidewalk Not Surveyed	Brown line		
Missing Sidewalk Gap	Pink line		
No Sidewalk on Block	Blue line		

Cross Slope

- 2 - 3%
- 3.01 - 4%
- 4.01 - 5%
- 5.01% - 6%
- 6.01 - 7%
- 7.01 - 8%
- 8.01 - 9%
- 9.01 - 10%
- 10.01 - 12%
- > 12%

Running Slope

- 5 - 8.33%
- 8.34% - 10%
- 10.01 - 12.5%
- > 12.5%

*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.