




ADA Survey Summary			ADA Compliance Cost Estimate *				Intersection Inventory & Compliance Cost Estimate								
Item	Description	Quantity	Item	Description	Quantity	Unit Price	Item Cost	Item	Description	Total Count	Non Compliant Count	Cost			
1	Heavings less than 1"	3 EA	1	Heavings less than 1"	2 EA	\$ 100.00	\$ 200.00	Curb Ramps	0	0	\$ 0.00	●	Heavings < 1" (Excluded)***	●	Heavings < 1"
2	Heavings 1" or greater	0 EA	2	Heavings 1" or greater	0 EA	\$ 400.00	\$ 0.00	Island Curb Cuts	0	0	\$ 0.00	●	Heavings ≥ 1" (Excluded)***	●	Heavings ≥ 1"
3	Uneven Heavings	0 EA	3	Uneven Heavings	0 EA	\$ 400.00	\$ 0.00	Signal Push Buttons	0	0	\$ 0.00	●	Uneven Heaving (Excluded)***	●	Uneven Heaving
4	Heaving Clusters	0 SY	4	Heaving Clusters	0 SY	\$ 75.00	\$ 0.00	Transit Stops	0	0	\$ 0.00	—	Heaving Clusters (Excluded)	—	Heaving Clusters
5	Sidewalk Joint Gaps	0 EA	5	Sidewalk Joint Gaps	0 EA	\$ 200.00	\$ 0.00	Railroad Crossings	0	0	\$ 0.00	▲	Sidewalk Joint Gap (Excluded)***	▲	Sidewalk Joint Gap
6	Miscellaneous Obstruction	0 EA	6	Miscellaneous Obstruction	0 EA	\$ 1500.00	\$ 0.00	Accessible Parking Spaces	0	0	\$ 0.00	■	Miscellaneous Obstruction	◆	Commercial Entrance
7	Missing Sidewalk Obstruction	0 EA	7	Missing Sidewalk Obstruction	0 EA	\$ 200.00	\$ 0.00	Intersection SubTotal:			\$ 0.00	■	Missing Sidewalk Obstruction	◆	Residential Entrance
8	Other Obstruction	0 EA	8	Other Obstruction	0 EA	\$ 500.00	\$ 0.00					■	Other Obstruction	✚	Commercial Entrance (within slope violation)
9	Pole Post Hydrant Obstruction	0 EA	9	Pole Post Hydrant Obstruction	0 EA	\$ 5000.00	\$ 0.00					■	Pole Post Hydrant Obstruction	✚	Residential Entrance (within slope violation)
10	Ponding Obstruction	0 EA	10	Ponding Obstruction	0 EA	\$ 400.00	\$ 0.00					■	Ponding Obstruction		
11	Sidewalk Joint Obstruction	0 EA	11	Sidewalk Joint Obstruction	0 EA	\$ 100.00	\$ 0.00					■	Sidewalk Joint Obstruction	■	Cross Slope
12	Sign Obstruction	0 EA	12	Sign Obstruction	0 EA	\$ 150.00	\$ 0.00					■	Sign Obstruction	■	2 - 3%
13	Storm Grate Obstruction	0 EA	13	Storm Grate Obstruction	0 EA	\$700.00	\$ 0.00					■	Storm Grate Obstruction	■	7.01 - 8%
14	Transit Obstruction	0 EA	14	Transit Obstruction	0 EA	\$500.00	\$ 0.00					■	Transit Obstruction	■	3.01 - 4%
15	Traffic Obstruction	0 EA	15	Traffic Obstruction	0 EA	\$2000.00	\$ 0.00					■	Traffic Obstruction	■	8.01 - 9%
16	Tree Obstruction	0 EA	16	Tree Obstruction	0 EA	\$500.00	\$ 0.00					■	Tree Obstruction	■	4.01 - 5%
17	Utility Obstruction	0 EA	17	Utility Obstruction	0 EA	\$1500.00	\$ 0.00					■	Utility Obstruction	■	9.01 - 10%
18	Vegetation Obstruction - Low	0 EA	18	Vegetation Obstruction - Low	0 EA	\$150.00	\$ 0.00					■	Vegetation Obstruction - Low	■	5.01% - 6%
19	Vegetation Obstruction - Overhead	1 EA	19	Vegetation Obstruction - Overhead	1 EA	\$150.00	\$ 150.00					■	Vegetation Obstruction - Overhead	■	10.01 - 12%
20	Commercial Entrance	0 EA	20	Commercial Entrance (within slope violation)	0 EA	\$ 5000.00	\$ 0.00					■	Commercial Entrance	■	6.01 - 7%
21	Residential Entrance	0 EA	21	Residential Entrance (within slope violation)	0 EA	\$ 3000.00	\$ 0.00					■	Residential Entrance	■	> 12%
22	Total Sidewalk Length Assessed	196.751 LF	22	Running Slope Violations**	0 SY	\$ 75.00	\$ 0.00					■	Running Slope	■	Cross Slope
23	Average Sidewalk Width	48 IN	23	Cross Slope Violations	40.228 SY	\$ 75.00	\$ 3017.00					■	Cross Slope	■	2 - 3%
24	No Sidewalk on Block (Approx.)	206.522 LF	24	Running and Cross Slope Violations	41.381 SY	\$ 75.00	\$ 3104.00					■	Running Slope	■	7.01 - 8%
25	Missing Sidewalk Gaps (Approx.)	0 LF	25	Missing Sidewalk Gaps (Approx.)	0 LF	\$ 41.67	\$ 0.00					■	Running Slope	■	8.01 - 9%
26	Poor Surface Condition (Approx.)	0 LF	26	Poor Surface Condition (Approx.)	0 LF	\$ 41.67	\$ 0.00					■	Running Slope	■	9.01 - 10%
27	Buried Sidewalk (Approx.)	0 LF	27	Buried Sidewalk (Approx.)	0 LF	\$ 41.67	\$ 0.00					■	Running Slope	■	5.01% - 6%
				Sidewalk SubTotal:		\$ 6471.00						■	Running Slope	■	10.01 - 12%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5%
												■	Running Slope	■	> 12.5