


SUMMERTREE_LN

An aerial photograph of a road. A yellow dashed line runs diagonally across the frame. A wheelchair symbol is visible on the left side of the road. The text "NTNWKX" is written in large, bold, yellow letters with a black outline, oriented vertically along the road.



*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

**Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.

***Note: Excluded items are violations that occur in areas with slope violations and have been excluded from the cost estimate.