



| ADA Survey Summary                   |            |                                                  |            |             |             |
|--------------------------------------|------------|--------------------------------------------------|------------|-------------|-------------|
| Item Description                     | Quantity   | Item Description                                 | Quantity   | Unit Price  | Item Cost   |
| 1 Heavings less than 1"              | 3 EA       | 1 Heavings less than 1"                          | 0 EA       | \$ 100.00   | \$ 0.00     |
| 2 Heavings 1" or greater             | 1 EA       | 2 Heavings 1" or greater                         | 0 EA       | \$ 400.00   | \$ 0.00     |
| 3 Uneven Heavings                    | 0 EA       | 3 Uneven Heavings                                | 0 EA       | \$ 400.00   | \$ 0.00     |
| 4 Heaving Clusters                   | 7.148 SY   | 4 Heaving Clusters                               | 0 SY       | \$ 75.00    | \$ 0.00     |
| 5 Sidewalk Joint Gaps                | 0 EA       | 5 Sidewalk Joint Gaps                            | 0 EA       | \$ 200.00   | \$ 0.00     |
| 6 Miscellaneous Obstruction          | 0 EA       | 6 Miscellaneous Obstruction                      | 0 EA       | \$ 1500.00  | \$ 0.00     |
| 7 Missing Sidewalk Obstruction       | 0 EA       | 7 Missing Sidewalk Obstruction                   | 0 EA       | \$ 200.00   | \$ 0.00     |
| 8 Other Obstruction                  | 0 EA       | 8 Other Obstruction                              | 0 EA       | \$ 500.00   | \$ 0.00     |
| 9 Pole Post Hydrant Obstruction      | 0 EA       | 9 Pole Post Hydrant Obstruction                  | 0 EA       | \$ 5000.00  | \$ 0.00     |
| 10 Ponding Obstruction               | 0 EA       | 10 Ponding Obstruction                           | 0 EA       | \$ 400.00   | \$ 0.00     |
| 11 Sidewalk Joint Obstruction        | 0 EA       | 11 Sidewalk Joint Obstruction                    | 0 EA       | \$ 100.00   | \$ 0.00     |
| 12 Sign Obstruction                  | 0 EA       | 12 Sign Obstruction                              | 0 EA       | \$ 150.00   | \$ 0.00     |
| 13 Storm Grate Obstruction           | 0 EA       | 13 Storm Grate Obstruction                       | 0 EA       | \$700.00    | \$ 0.00     |
| 14 Transit Obstruction               | 0 EA       | 14 Transit Obstruction                           | 0 EA       | \$500.00    | \$ 0.00     |
| 15 Traffic Obstruction               | 0 EA       | 15 Traffic Obstruction                           | 0 EA       | \$2000.00   | \$ 0.00     |
| 16 Tree Obstruction                  | 0 EA       | 16 Tree Obstruction                              | 0 EA       | \$500.00    | \$ 0.00     |
| 17 Utility Obstruction               | 0 EA       | 17 Utility Obstruction                           | 0 EA       | \$1500.00   | \$ 0.00     |
| 18 Vegetation Obstruction - Low      | 0 EA       | 18 Vegetation Obstruction - Low                  | 0 EA       | \$150.00    | \$ 0.00     |
| 19 Vegetation Obstruction - Overhead | 0 EA       | 19 Vegetation Obstruction - Overhead             | 0 EA       | \$150.00    | \$ 0.00     |
| 20 Commercial Entrance               | 0 EA       | 20 Commercial Entrance (within slope violation)  | 0 EA       | \$ 5000.00  | \$ 0.00     |
| 21 Residential Entrance              | 5 EA       | 21 Residential Entrance (within slope violation) | 5 EA       | \$ 3000.00  | \$ 15000.00 |
| 22 Total Sidewalk Length Assessed    | 389.476 LF | 22 Running Slope Violations**                    | 4.661 SY   | \$ 75.00    | \$ 350.00   |
| 23 Average Sidewalk Width            | 48 IN      | 23 Cross Slope Violations                        | 120.094 SY | \$ 75.00    | \$ 9007.00  |
| 24 No Sidewalk on Block (Approx.)    | 359.622 LF | 24 Running and Cross Slope Violations            | 19.711 SY  | \$ 75.00    | \$ 1478.00  |
| 25 Missing Sidewalk Gaps (Approx.)   | 0 LF       | 25 Missing Sidewalk Gaps (Approx.)               | 0 LF       | \$ 41.67    | \$ 0.00     |
| 26 Poor Surface Condition (Approx.)  | 0 LF       | 26 Poor Surface Condition (Approx.)              | 0 LF       | \$ 41.67    | \$ 0.00     |
| 27 Buried Sidewalk (Approx.)         | 0 LF       | 27 Buried Sidewalk (Approx.)                     | 0 LF       | \$ 41.67    | \$ 0.00     |
|                                      |            | Sidewalk SubTotal:                               |            | \$ 25835.00 |             |

| Intersection Inventory & Compliance Cost Estimate * |             |                     |         |
|-----------------------------------------------------|-------------|---------------------|---------|
| Item Description                                    | Total Count | Non Compliant Count | Cost    |
| Curb Ramps                                          | 0           | 0                   | \$ 0.00 |
| Island Curb Cuts                                    | 0           | 0                   | \$ 0.00 |
| Signal Push Buttons                                 | 0           | 0                   | \$ 0.00 |
| Transit Stops                                       | 0           | 0                   | \$ 0.00 |
| Railroad Crossings                                  | 0           | 0                   | \$ 0.00 |
| Accessible Parking Spaces                           | 0           | 0                   | \$ 0.00 |
| Intersection SubTotal:                              |             |                     | \$ 0.00 |

Corridor Total:

\$25835.00

Curb Ramps - Compliant

Curb Ramps - Non Compliant

Island Curb Cuts - Compliant

Island Curb Cuts - Non Compliant

Signals - Compliant

Signals - Non Compliant

Transit Stops - Compliant

Transit Stops - Non Compliant

Railroad Crossings - Compliant

Railroad Crossings - Non Compliant

Accessible Parking - Compliant

Accessible Parking - Non Compliant

Curb Ramps - Adjacent

Island Curb Cuts - Adjacent

Signals - Adjacent

Transit Stops - Adjacent

Railroad Crossings - Adjacent

Accessible Parking - Adjacent

Heavings < 1" (Excluded)\*\*\*Heavings ≥ 1" (Excluded)\*\*\*Uneven Heaving (Excluded)\*\*\*Heaving Clusters (Excluded)Sidewalk Joint Gap (Excluded)\*\*\*Miscellaneous ObstructionMissing Sidewalk ObstructionOther ObstructionPole Post Hydrant ObstructionPonding ObstructionSidewalk Joint ObstructionSign ObstructionStorm Grate ObstructionTransit ObstructionTraffic ObstructionTree ObstructionUtility ObstructionVegetation Obstruction - LowVegetation Obstruction - OverheadSidewalk Collection PathAdjacent Sidewalk Collection PathBuried SidewalkSidewalk Not SurveyedMissing Sidewalk GapNo Sidewalk on Block

Heavings < 1"Heavings ≥ 1"Uneven HeavingHeaving ClustersSidewalk Joint GapCommercial EntranceResidential EntranceCommercial Entrance (within slope violation)Residential Entrance (within slope violation)

Cross Slope

2 - 3%7.01 - 8%

3.01 - 4%8.01 - 9%

4.01 - 5%9.01 - 10%

5.01% - 6%10.01 - 12%

6.01 - 7%> 12%

Running Slope

5 - 8.33%8.34% - 10%

10.01 - 12.5%> 12.5%

\*Note: ADA pedestrian issues have been identified and quantified in the ADA Survey Summary. There are instances where multiple issues can be resolved with a single corrective measure. The ADA Compliance Cost Estimate reflects the best estimation of quantities and cost to resolve all identified ADA issues.

\*\*Note: Additional investigation may be warranted when sidewalk running slope issues exist within the right-of-way.