

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

20.0

Intersection ID: 9828 Main Street: KANIMBLA_DR Cross Street: TUCKASEEGEE_RD Location: W

ADA ID: 000E2DF57729 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Compliance Description

Ramp Length (in)

Ramp Width (in)

Ramp Slope (%)

Flare Type LT

Ramp XSlope (%)

Flare Slope LT (%)

Flare Traversable LT?

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Any Obstructions?

Obstruction Type

N/A

Yes

No

Yes N/A

1600.00

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)

Data

123.0

70.0

12.4

1.5

N/A

N/A

N/A

0.0

N/A N/A



Street 1 Name KANIMBLA DR
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

<u> </u>	
20,000	Possible Solutions:
No. of the second	Remove & Replace Entire Ramp.
	Surveyor Notes:
A A	N/A
	PROW/ADA:
No. of the last of	R304.2.2

	3 10		
		1	
-			
		DE VERSON	

Total Cost:





DWS Contrast? 0.0 N/A N/A 0.0 N/A DWS Length (in) N/A N/A DWS Full Width? 0.0 N/A N/A N/A DWS Offset LT (in) N/A N/A N/A DWS Offset RT (in) N/A 0.0 N/A Gutter Slope (%) N/A 0.0 N/A Gutter X Slope (%) N/A No Road Slope (%) 0.6 To E Road X Slope (%) 10.4 N/A Clear Space? N/A 0.6 N/A N/A Clear Space to XWalk (in) 10.4 N/A Storm Grate/Utility Hazard? N/A N/A Storm Grate/Utility Type N/A N/A Surface Condition? (G/P) Yes Good

Curb Slope (%)