cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16155	Main Str	eet: DEWITT I N	Cross	Street.	TRYCLAN DR			Location:	SW		
	Main Street: DEWITT_LN			Cross Street: TRYCLAN_DR							
ADA ID: 00128384193A	03A Ramp Type: PerpDiag		Initial P	Initial Pass/Fail: Fail Overall Compliance			ice: N	o Severity Score:	21.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	is.	Possible Solutions:		Compliance Description		Data Compliance Description			Data		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	8.6		
		Two New Directional Ramps or		No	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	0.7		
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
	Contraction and			N/A	Shared Landing?	N/A					
	W and the	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
		Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		
					X Walk 1 Direction	To SE		X Walk 2 Direction	To N		
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	DEWITT LN				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	0.2		
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	0.3		
Street 2 Name	TRYCLAN DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
Stop Condition-Street 1	StopSign				Road Slope (%)	0.1	N/A	Clear Space?	N/A		
					Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A		
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type			
						N/A			N/A		
							Yes	Surface Condition? (G/P)	Good		



