

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interception ID: 7045	Main Streets KNOLL OPEST DD					Leastion	05			
Intersection ID: 7845	wain Str	Main Street: KNOLLCREST_DR			RIDGELEY_DR			Location:	SE	
ADA ID: 001935C4F898	Ramp Ty	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description Data			Compliance Description		Data		
	A AND	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	51.0	Yes	Ramp Slope (%)	7.7	
	Marrie A			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.9	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198 - 198	-			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	1990			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Con Con				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
the second	12 10	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	Street	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
8	1 NOTES			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
Sel Martin				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	At the h	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	1000			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	· Mar				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
	1 20.0			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	KNOLLCREST DR				X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	6.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

**Yes** Surface Condition? (G/P)

Good

