

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9290 Mai	Main Street, CRIER PD		Cross Street: OLD CRIED DD			Location	NW	
	Main Street: GRIER_RD		Cross Street: OLD_GRIER_RD			Location:		
ADA ID: 0058AD57E5A9 Ramp Type: Perp		Initial Pass/	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Con	Compliance Description Data Complia			liance Description	Data	
	Remove & Replace Entire Ram	p. N/A	Ramp Length (in)	84.0	Yes	Ramp Slope (%)	5.4	
GRIERLAD	and the	No	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	1.3	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
6	and the second se	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
E BE		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A COLO COLO	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
AT AD		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
E to	18	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
7	1 33	N/A	Shared Landing?	N/A				
Little Free Cont	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
The second and the second second		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name OLD GRIEF	RD		X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	lone		X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A		Road Slope (%)	N/A	N/A	Clear Space?	N/A	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$	1850.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	

es Surface Condition? (G/P)

Good

