

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



N/A

Good

12.8

Surface Condition? (G/P)

Curb Slope (%)

Intersection ID: 3909 Main Street: BENTHAVEN LN Cross Street: CHIMNEY RIDGE TL Location: SW **Overall Compliance: No Severity Score:** 35 ADA ID: 009450E9F34D Ramp Type: Directional1 Initial Pass/Fail: Fail

## **Codes/Mitigation Info/Possible Solution** Field Measurements/Component Compliance Compliance Description Possible Solutions: Data Compliance Description Data N/A N/A Ramp Length (in) 35.0 Grade Break? N/A Remove & Replace Entire Ramp. 46.0 N/A No Ramp Width (in) Grade Break Slope (%) 0.0 N/A No Ramp Slope (%) 12.3 Grade Break XSlope (%) 0.0 Ramp XSlope (%) 2.1 No N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) 0.0 Surveyor Notes: N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A 0.0 N/A DWS Provided? N/A N/A Landing Length (in) N/A N/A Landing Width (in) 0.0 N/A **DWS Contrast?** N/A N/A Landing Slope (%) 0.0 N/A DWS Length (in) N/A N/A N/A Landing X Slope (%) 0.0 DWS Full Width? N/A PROW/ADA: N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A R304.5.1, R304.2.2, R304.5.3 N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Road Slope (%) 0.6 **CHIMNEY RIDGE TL** Street 1 Name X Walk 1 Direction To N Road X Slope (%) 1.6 Stop Condition-Street 1 StopSign X Walk 1 Width (in) N/A Clear Space? N/A N/A 0.6 N/A Street 2 Name X Walk 1 Slope (%) Clear Space to XWalk (in) N/A Stop Condition-Street 2 N/A X Walk 1 X Slope (%) 1.6 N/A Storm Grate/Utility Hazard? N/A N/A Ramp inside XWalk1? N/A Storm Grate/Utility Type

1600.00





Total Cost:



N/A

Any Obstructions?

**Obstruction Type** 

N/A

Yes

N/A N/A