

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.9

0.2

N/A

Good

Intersection ID: 12574 Main Street: WILKINSON BV **Cross Street: HIGHLAND ST** Location: NW **Overall Compliance: No** ADA ID: 00AAD11FE3A2 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

43.0

36.0

N/A

No

To E

N/A

0.1

3.4

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



HIGHLAND ST Street 1 Name Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compli	ance	Description	
Remove & Replace Entire Ramp.	N/A	N/A Ramp Length (in)		
·	No	Ramp Width (in)		
	N/A	Flare Slope LT (%)		
	N/A			
	N/A			
	N/A	Land	ing Length (in)	
Surveyor Notes:	N/A	Land	ing Width (in)	
N/A	N/A	Landing Slope (%)		
	N/A	Land	ing X Slope (%)	
	N/A	Land	ing Curb? (Y/N)	
	N/A	Share	ed Landing?	
PROW/ADA:	N/A	Gutte	er Ponding?	
Not Found, R304.5.1	N/A	Gutte	er Lip Ht (in)	
,	N/A	Paint	ed X Walk1?	
		X Wa	lk 1 Direction	
	N/A	X Wa	ılk 1 Width (in)	
		X Wa	ılk 1 Slope (%)	
		X Wa	ılk 1 X Slope (%	
	N/A	Ram	p inside XWalk1	
		Road	l Slope (%)	
		Poad	I Y Slone (%)	





Total Cost:



N/A

1850.00