

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 16182	Main Street: MONROE_RD	Cross Street: SHADE VALLEY_RD	Location: NE
ADA ID: 00F45D3D6CB1	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 22.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	57.0	
			No	Ramp Width (in)	41.0	
			No	Ramp Slope (%)	8.6	
			No	Ramp XSlope (%)	2.3	
			N/A	Flare Type LT	N/A	
			N/A	Flare Slope LT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	
			N/A	Landing Length (in)	0.0	
			N/A	Landing Width (in)	0.0	
			N/A	Landing Slope (%)	0.0	
			N/A	Landing X Slope (%)	0.0	
			N/A	Landing Curb? (Y/N)	N/A	
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	0.0	
			N/A	Gutter Lip Ht (in)	0.0	
			N/A	Painted X Walk1?	No	
				X Walk 1 Direction	To NW	
				X Walk 1 Width (in)	N/A	
				X Walk 1 Slope (%)	0.1	
				X Walk 1 X Slope (%)	6.5	
Surveyor Notes: N/A			N/A	Ramp inside XWalk1?	N/A	
			N/A	Any Obstructions?	N/A	
PROW/ADA: R304.5.1, R304.2.2, R304.5.3				Obstruction Type		
			Yes	Surface Condition? (G/P)	Good	
			N/A	Curb Slope (%)	12.1	
Street 1 Name	SHADE VALLEY RD					
Stop Condition-Street 1	StopSign					
Street 2 Name	N/A					
Stop Condition-Street 2	N/A					
Total Cost:	\$	1600.00				

