cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27720	Main Street: OLD_ACRES_CT			Cross Street: HAMPSHIRE_HILL_RD				Location:	NW
ADA ID: 010F88FFFE2D	Ramp Ty	Ramp Type: PerpDiag			ail: Fail Overall C	o Severity Score:	25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:					Data Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.5
		Two New Directional Ramps or		Yes	Ramp Width (in)	55.5		Ramp XSlope (%)	9.2
		Equivalent.		N/A	Flare Type LT	N/A		Flare Type RT	N/A
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
The second se				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
OLD AGRES OT		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second se				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		DWS Onset (III)	11/2
Martin Martin		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
					-				
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
	100000000000000000000000000000000000000			N/A	Painted X Walk1?	No Tu O	N/A	Painted X Walk2?	No Tu F
	THE ST AND				X Walk 1 Direction	To S		X Walk 2 Direction	To E
	J & Star Jim Market	N		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	OLD ACRES CT				X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	5.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.8		X Walk 2 X Slope (%)	4.5
Street 2 Name	HAMPHIRE HILL RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	10.7	N/A	Clear Space?	N/A
					Road X Slope (%)	5.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good





