

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: LAKEWOOD_EDGE_DR Cross Street: WYLIE_MEADOW_LN Location: Intersection ID: 4278 NE

ADA ID: 01157630BC7	DA ID: 01157630BC7D Ramp Type: Directional1		Initia	I Pass/F	ail: Fail Overa	I Compliar	ice: N	o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Comp	liance Description	Data
		Remove & Replace Entire Rai	np.	N/A	Ramp Length (in)	104.0	N/A	Grade Break?	N/A
	EDOM Tru	·	•	Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
				No	Ramp Slope (%)	8.5	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	4.9			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
[<u>2</u>	E and I M	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
WALE	MOON JESS			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	₽.			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	\			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	\			N/A	Painted X Walk1?	No		Road Slope (%)	0.2
Street 1 Name	WYLIE MEADOWS LN				X Walk 1 Direction	To S		Road X Slope (%)	2.8
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.8	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	14.1





