


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: N/A		Main Street: STATESVILLE_RD		Cross Street: N/A		Location:		NW	
ADA ID: 013A67FEF8C9		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance		Description		Data	
		Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		80.0	
				Yes		Ramp Width (in)		67.0	
				Yes		Ramp Slope (%)		5.4	
				No		Ramp XSlope (%)		3.0	
				N/A		Flare Type LT		N/A	
				N/A		Flare Slope LT (%)		N/A	
				N/A		Flare Traversable LT?		N/A	
				N/A		Landing Length (in)		0.0	
				N/A		Landing Width (in)		0.0	
Surveyor Notes:  N/A				N/A		Flare Type RT		N/A	
				N/A		Flare Slope RT (%)		0.0	
				N/A		Flare Traversable RT?		N/A	
				N/A		DWS Provided?		N/A	
				N/A		DWS Contrast?		N/A	
				N/A		DWS Length (in)		N/A	
				N/A		DWS Full Width?		N/A	
				N/A		DWS Offset LT (in)		N/A	
				N/A		DWS Offset RT (in)		N/A	
				N/A		Gutter Ponding?		0.0	
PROW/ADA:  R304.5.3				N/A		Gutter Lip Ht (in)		0.0	
				N/A		Painted X Walk1?		No	
						X Walk 1 Direction		To S	
						X Walk 1 Width (in)		N/A	
						X Walk 1 Slope (%)		0.3	
						X Walk 1 X Slope (%)		1.9	
				N/A		Ramp inside XWalk1?		N/A	
				N/A		Any Obstructions?		N/A	
						Obstruction Type		Yes	
								N/A	
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			
						N/A			

