## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 24099	Main Street: ARBOR_POINTE_DR			Street:	FOUR_ACRE_CT	Location:	SW		
ADA ID: 016F53017EDF	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
C. A.		Remove & Replace Curb Ram	With	N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	11.5
		Two New Directional Ramps or		No	Ramp Width (in)	40.0	No	Ramp XSlope (%)	4.1
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ARBOR POINTE DR				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A State of the sta		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
198 Alla Alla		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	19 31-1	R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To E		X Walk 2 Direction	To N
	THE REAL PROPERTY AND INCOMENTS			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	FOUR ACRE CT	•			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	1.9
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	2.8
Street 2 Name	ARBOR POINTE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.4	N/A	Clear Space?	N/A
					Road X Slope (%)	2.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
1		ψ				N/A		cloth Grato/Gunty Type	N/A
						IN/A			17/5

**Yes** Surface Condition? (G/P)

Good

