


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12808	Main Street: HICKORY_GROVE_RD	Cross Street: SPRING_LAKE_DR	Location: E
ADA ID: 017231C5508E	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 26.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	Possible Solutions:		Compliance			Description			Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)		60.0	No	Ramp Slope (%)		14.8
			Yes	Ramp Width (in)		50.0	Yes	Ramp XSlope (%)		2.2
			N/A	Flare Type LT		N/A	N/A	Flare Type RT		N/A
			N/A	Flare Slope LT (%)		N/A	N/A	Flare Slope RT (%)		N/A
			N/A	Flare Traversable LT?		N/A	N/A	Flare Traversable RT?		N/A
			N/A	Landing Length (in)		N/A	N/A	DWS Provided?		N/A
			N/A	Landing Width (in)		N/A	N/A	DWS Contrast?		N/A
			N/A	Landing Slope (%)		N/A	N/A	DWS Length (in)		N/A
			N/A	Landing X Slope (%)		N/A	N/A	DWS Full Width?		N/A
Surveyor Notes:		N/A			N/A	Landing Curb? (Y/N)		N/A	N/A	N/A
PROW/ADA:		R304.2.2			N/A	Shared Landing?		N/A		
					N/A	Gutter Ponding?		N/A	N/A	N/A
					N/A	Gutter Lip Ht (in)		N/A	N/A	N/A
					N/A	Painted X Walk1?		No	N/A	N/A
						X Walk 1 Direction		To W	N/A	
					N/A	X Walk 1 Width (in)		N/A	N/A	N/A
						X Walk 1 Slope (%)		1.7	N/A	
						X Walk 1 X Slope (%)		4.1	N/A	
					N/A	Ramp inside XWalk1?		N/A	N/A	N/A
						Road Slope (%)		N/A	N/A	N/A
						Road X Slope (%)		N/A	N/A	N/A
					N/A	Any Obstructions?		N/A	N/A	N/A
						Obstruction Type				
								N/A	N/A	
								Yes	Good	
Street 1 Name		SPRING LAKE DR								
Stop Condition-Street 2		None								
Street 2 Name		N/A								
Stop Condition-Street 1		N/A								
Total Cost:		\$ 1850.00								

