## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



I

Curb Slope (%)

12.1

									Leastien	NE
Intersection ID: N/A	Main Street: HOLT_ST				Cross Street: THE_PLAZA					
ADA ID: 031E08E3D3A7	ID: 031E08E3D3A7 Ramp Type: Combination2Diag			Initia	Initial Pass/Fail: Fail Overall Complian			nce: No Severity Score:		0
Codes/Mitigation Info/Possible Solution Field Measurement								ompo	nent Compliance	
	1 - 0	Possible Solutions:			Compliance Description		Data	Data Compliance Description		
		Remove & Replace Cur	rb Ram	np With	N/A	Ramp Length LT (in)	69.0	N/A	Ramp Length RT (in)	53.0
		Two New Directional R	amps o	or	No	Ramp Width LT (in)	39.0	No	Ramp Width RT (in)	37.5
		Equivalent.			Yes	Ramp Slope LT (%)	3.4	Yes	Ramp Slope RT (%)	5.5
B	/				No	Ramp XSlope LT (%)	4.5	No	Ramp XSlope RT (%)	3.5
	a state of the				N/A	Ramp Length (in)	28.0	Yes	Ramp Slope (%)	5.4
					Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.5
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A A A A A A A A A A A A A A A A A A A	1				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
TUE	< ·				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
5	11 10				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
6	A.	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	E A	Not Found, R304.5.1, R	304.5.3	3	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		, ,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	A				N/A	Shared Landing?	N/A			
	120				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	HOLT_ST				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	None					X Walk 1 Direction	To W		X Walk 2 Direction	To S
Stop Condition-Street 2	THE_PLAZA					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	5.3
						X Walk 1 X Slope (%)	6.1		X Walk 2 X Slope (%)	0.1
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	4.6		Clear Space?	N/A
						Road X Slope (%)	7.7	N/A	Clear Space to XWalk (in)	N/A
			Co.	and a		La La		N/A	Any Obstruction?	N/A
									Obstruction Type	
	T I									N/A
		The state of the second s	-					N/A	Storm Grate/Utility Hazard?	N/A
									Storm Grate/Utility Type	IN/A
				9/ /						N/A
	-		1	1		Var Star		Yes	Surface Condition? (G/P)	Good