

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11640 Main Street: E_W_T_HARRIS_BV Cross Street: WILLIAMS_RD Location: NE

ADA ID: 037716AC582E Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

E W T HARRIS BV None WILLIAMS RD StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
Not Found, R304.2.2

Total Cost: \$ 3200.00

Fleid Measurements/Component Compliance						
Compliance Description		Data	Compl	iance	Description	Data
N/A	Ramp Length (in)	58.5	No	Ramp	Slope (%)	9.3
Yes	Ramp Width (in)	48.0	Yes	Ramp	XSlope (%)	0.2
N/A	Flare Type LT	N/A	N/A Flare Type RT		N/A	
N/A	Flare Slope LT (%)	N/A	N/A	N/A Flare Slope RT (%)		N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	Yes	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	To SE
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.5		X Wa	lk 2 Slope (%)	1.3
	X Walk 1 X Slope (%)	0.3		X Wa	lk 2 X Slope (%)	0.8
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
	Road Slope (%)	0.3	N/A	Clear	Space?	N/A
	Road X Slope (%)	0.1	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A

N/A

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







Obstruction Type