

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10036962	Main Street: S_TRYON_ST			Cross	Cross Street: N/A				Location:	NW
ADA ID: 045C92243F6D	Ramp Ty	Ramp Type: Combination1			Initial Pass/Fail: Fail Overall Complian				o Severity Score:	21.25
Codes/Mi	tigation Info	/Possible Solution				Field Measure	ments/C	ompo	nent Compliance	
		Possible Solutions:			Compliance Description		Data Compl		liance Description	Data
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	. /	Remove & Replace En	ntire Rar	mp.	N/A	Ramp Length LT (in)	44.0	N/A	Ramp Length RT (in)	53.0
					Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
III IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII					Yes	Ramp Slope LT (%)	3.9	Yes	Ramp Slope RT (%)	6.5
					Yes	Ramp XSlope LT (%)	2.0	Yes	Ramp XSlope RT (%)	0.5
	and the second				N/A	Ramp Length (in)	29.5	Yes	Ramp Slope (%)	8.0
	10-				No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	5.5
6		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E.	MEDIAN ACROSS S TRYON ST, LT			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		RP < 5%		,	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
NON					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Ballun		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		R304.5.1, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	The second	·····, ····			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6					N/A	Shared Landing?	N/A			
Lost to an the state					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	ENTRANCE				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
l						X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A
I						X Walk 1 X Slope (%)	6.1		X Walk 2 X Slope (%)	N/A
l		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
I						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					1/1			N/A	Any Obstruction?	N/A
The Stop			TT	Bullanda.					Obstruction Type	
OIUP	* 1 1	Till altra		And the second public						N/A
								N/A	Storm Grate/Utility Hazard?	N/A

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 2.5





