## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·									
Intersection ID: 47280 Main Street: SAVANNAH_HILLS_DR			Cross	Cross Street: LAMPLIGHTER_CLOSE_DR				Location:	SW
ADA ID: 0467237BA6BA Ramp Type: PerpDiag			Initial P	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
The second second	Roo I I I I I	Possible Solutions:					Compliance Description		Data
		Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent.	Nith	N/A	Ramp Length (in)	49.0		Ramp Slope (%)	9.3
			<b>VVILII</b>	No	Ramp Width (in)	45.0		Ramp XSlope (%)	6.1
				N/A	Flare Type LT	-10.0 N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
- The second sec				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
SAVANNAR PER				N/A		N/A	N/A	DWS Provided?	N/A N/A
		Cumunum Ninten			Landing Length (in)		N/A	DWS Contrast?	
ATTAL CONTRACT		Surveyor Notes:		N/A	Landing Width (in)	N/A			N/A
	5. B 6	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	El Trance			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
All are some the solar	3			N/A	Shared Landing?	N/A			
ALTER A		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Frank all	Not Found, R304.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
R304.5.3				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To E		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LAMPLIGHTER CLOSE DR				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	5.3
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	2.6
Street 2 Name	SAVANNAH HILLS DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	5.2	N/A	Clear Space?	N/A
					Road X Slope (%)	1.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		· · · · · · · · · · · · · · · · · ·				N/A			N/A
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

