

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

0.7

1.2

N/A

N/A

N/A

N/A

5.8

Good

Intersection ID: 21326 Main Street: PROVIDENCE_RD Cross Street: TURNBRIDGE_RD Location: SW

ADA ID: 04E5FE29DF83 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

Compliance Description

Grade Break?

Grade Break Slope (%)

Data

51.5

71.5



Street 1 Name
TURNBRIDGE RD
Stop Condition-Street 1
StopSign
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

No N/A 1600.00

N/A

Yes

Compliance Description

Ramp Length (in)

Ramp Width (in)

N/A Yes Ramp Slope (%) 5.3 Grade Break XSlope (%) Ramp XSlope (%) 3.1 Flare Type LT N/A N/A Flare Type RT Flare Slope LT (%) N/A N/A Flare Slope RT (%) Flare Traversable LT? N/A N/A Flare Traversable RT? 0.0 N/A **DWS Provided?** Landing Length (in) Landing Width (in) 0.0 N/A **DWS Contrast?** Landing Slope (%) 0.0 N/A DWS Length (in) N/A DWS Full Width? Landing X Slope (%) 0.0 Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) Shared Landing? N/A N/A DWS Offset RT (in) **Gutter Ponding?** 0.0 N/A Gutter Slope (%) Gutter Lip Ht (in) 0.0 N/A Gutter X Slope (%) Painted X Walk1? No Road Slope (%) X Walk 1 Direction To N Road X Slope (%) X Walk 1 Width (in) N/A Clear Space? 0.7 N/A X Walk 1 Slope (%) Clear Space to XWalk (in) X Walk 1 X Slope (%) 1.2 N/A Storm Grate/Utility Hazard? Ramp inside XWalk1? N/A Storm Grate/Utility Type N/A Any Obstructions? **Obstruction Type** Surface Condition? (G/P) Yes N/A N/A Curb Slope (%)





Total Cost:

