

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16805Main Street:N_SHARON_AMITY_RDCross Street:KELLY_STLocation:NWADA ID: 04F017F618CBRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:42.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

KELLY ST
Stop Condition-Street 2
StopSign
Street 2 Name
N SHARON AMITY RD
Stop Condition-Street 1
None

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
	Compliance Description		Data	Comp	liance Description	Data
	N/A	Ramp Length (in)	75.0	Yes	Ramp Slope (%)	5.2
	No	Ramp Width (in)	33.0	No	Ramp XSlope (%)	15.8
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	13.9
		X Walk 1 X Slope (%)	14.2		X Walk 2 X Slope (%)	0.4
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	10.7	N/A	Clear Space?	N/A
		Road X Slope (%)	12.1	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good





