

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 7636	Main Street: GEORGETOWN DR			Cross Street: ROSADA AV				Location:	Е
ADA ID: 0526F68DCED2	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:					liance Description	Data	
	N1	Remove & Replace Entire Ran	מח.	N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	7.7
				No	Ramp Width (in)	38.0	Yes	Ramp XSlope (%)	1.1
	and the second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	- be the			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
SORGETION		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
DR	and the second s			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Y No TO MER O				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	AND A			N/A	Shared Landing?	N/A			
The second second		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The second second		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	of the particular of			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	Jan B				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ROSADA AV				X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

