

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7945Main Street: DAVID_AVCross Street: LITTLE_ROCK_RDLocation: NADA ID: 05424297924ERamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 21.25

Onder (Mittingstion Info/Describe Collection

Codes/Mitigation Info/Possible Solution

Possible Solutions:



Street 1 Name DAVID AV
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

1 033IDIC COIGIIOTI3.		
Remove & Replace Entire Ramp.		
	N	
	N	
	1	
	N	
	1	
Surveyor Notes:	1	
N/A	1	
	1	
	1	
	1	
PROW/ADA:	1	
Not Found, R304.5.1, R304.2.2	N	
, ,	N	
	١	
	r	





Total Cost:



1850.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Compl	iance Description	Data		
N/A	Ramp Length (in)	80.0	No	Ramp Slope (%)	9.2		
No	Ramp Width (in)	42.0	Yes	Ramp XSlope (%)	0.0		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	96.0	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		