

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30565Main Street:CIRCLEGREEN\_DRCross Street:GREENCREEK\_DRLocation:NEADA ID: 05777573774FRamp Type:BlendTrans2Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

CIRCLEGREEN DR None GREENCREEK DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost: \$ 3200.00

	Comp	liance Description	Data Compliance Description			Data
	N/A	Ramp Length (in)	94.0	Yes	BlendTrans Slope (%)	4.8
	Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	7.3
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To W		X Walk 2 Direction	To S
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	3.4
		X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	3.1
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	2.8		Clear Space?	N/A
		Road X Slope (%)	5.3	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type		l	Storm Grate/Utility Type	
			N/A	l		N/A
				Yes	Surface Condition? (G/P)	Good
in the same	2			N/A	Curb Slope (%)	3.5





