

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A 0.0 0.0

> N/A 0.0 N/A N/A N/A N/A N/A N/A

1.8

N/A

N/A

N/A

N/A Good

N/A

Intersection ID: 15348Main Street: ARDSLEY_RDCross Street: S_KINGS_DRLocation: SWADA ID: 057AADB890ADRamp Type: Directional1Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A N/A

Curb Slope (%)



Street 1 Name
Stop Condition-Street 1
None
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solution		Field Measurements/Component Compnance					
Possible Solutions:			Compliance Description		Data	Data Compliance Description	
Remove & Replace Ent	ire Ram	ıp.	N/A	Ramp Length (in)	42.0	N/A	Grade Break?
·		•	Yes	Ramp Width (in)	52.0	N/A	Grade Break Slope (%)
			No	Ramp Slope (%)	12.5	N/A	Grade Break XSlope (%)
			Yes	Ramp XSlope (%)	0.9		
			N/A	Flare Type LT	N/A	N/A	Flare Type RT
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)
Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?
PODNING PREVENTED CURB			N/A	Landing Length (in)	0.0	N/A	DWS Provided?
SLOPE			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?
1			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)
			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?
PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)
R304.2.2			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)
			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)
			N/A	Painted X Walk1?	No		Road Slope (%)
				X Walk 1 Direction	To N		Road X Slope (%)
				X Walk 1 Width (in)	N/A		Clear Space?
				X Walk 1 Slope (%)	1.4	N/A	Clear Space to XWalk (in)
				X Walk 1 X Slope (%)	1.8	N/A	Storm Grate/Utility Hazard?
			N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type
			N/A	Any Obstructions?	N/A		
Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)





