


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 22470	Main Street: SHARON_VIEW_RD	Cross Street: BENTRIDGE_DR	Location: SW
ADA ID: 059E9F3AE764	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 37.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		<b>No</b>	Ramp Length (in)	<b>61.0</b>
			<b>Yes</b>	Ramp Width (in)	<b>48.0</b>
			<b>N/A</b>	Flare Type LT	<b>N/A</b>
			<b>N/A</b>	Flare Slope LT (%)	<b>N/A</b>
			<b>N/A</b>	Flare Traversable LT?	<b>N/A</b>
			<b>N/A</b>	Landing Length (in)	<b>N/A</b>
			<b>N/A</b>	Landing Width (in)	<b>N/A</b>
			<b>N/A</b>	Landing Slope (%)	<b>N/A</b>
			<b>N/A</b>	Landing X Slope (%)	<b>N/A</b>
<p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.2.2, R304.5.3</b></p>			<b>N/A</b>	Flare Type RT	<b>N/A</b>
			<b>N/A</b>	Flare Slope RT (%)	<b>N/A</b>
			<b>N/A</b>	Flare Traversable RT?	<b>N/A</b>
			<b>N/A</b>	DWS Provided?	<b>N/A</b>
			<b>N/A</b>	DWS Contrast?	<b>N/A</b>
			<b>N/A</b>	DWS Length (in)	<b>N/A</b>
			<b>N/A</b>	DWS Full Width?	<b>N/A</b>
			<b>N/A</b>	DWS Offset (in)	<b>N/A</b>
			<b>N/A</b>	Gutter Ponding?	<b>N/A</b>
			<b>N/A</b>	Gutter Lip Ht (in)	<b>N/A</b>
<p>Total Cost:</p> <p><b>\$ 3200.00</b></p>			<b>No</b>	Painted X Walk2?	<b>No</b>
			<b>To SE</b>	X Walk 2 Direction	<b>To NE</b>
			<b>N/A</b>	X Walk 2 Width (in)	<b>N/A</b>
			<b>1.3</b>	X Walk 2 Slope (%)	<b>5.9</b>
			<b>13.2</b>	X Walk 2 X Slope (%)	<b>7.3</b>
			<b>N/A</b>	Ramp inside XWalk2?	<b>N/A</b>
			<b>10.5</b>	Clear Space?	<b>N/A</b>
			<b>9.2</b>	Clear Space to XWalk (in)	<b>N/A</b>
			<b>N/A</b>	Storm Grate/Utility Hazard?	<b>N/A</b>
			<b>N/A</b>	Storm Grate/Utility Type	<b>N/A</b>
			<b>N/A</b>		<b>N/A</b>
			<b>Yes</b>	Surface Condition? (G/P)	<b>Good</b>

