


Intersection ID: 20158	Main Street: GAULEY_CR	Cross Street: GRIERS_FORK_DR	Location:	SE
ADA ID: 05CE8FDD0E22	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance								
	Possible Solutions:		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			Compliance	Description	Data	Compliance	Description	Data
	Surveyor Notes:		N/A			N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.9
	PROW/ADA:		R304.5.1			No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	1.0
						N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
						N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
						N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
						N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
						N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
						N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
						N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
					N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
						X Walk 1 Direction	To NE		X Walk 2 Direction	To NW	
					N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	3.0	
						X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)	1.3	
					N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	1.1	N/A	Clear Space?	N/A	
						Road X Slope (%)	2.6	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
						Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	

